

# ANNUAL SURVEYS.

Recd 21.8.75

No. in Reg. Book. **No.** 995 Survey held at **London** Date, first Survey **1873** Last Survey **July 31<sup>st</sup> 1875**  
 on the **S.S. State of Virginia** Master **Sadler**  
 Tonnage **24 1/3** Built at **Glasgow** When built **1873 - 3<sup>rd</sup> mo.**  
 By whom built **Len. & Co. S. Shipbuilders** Owners **State Line S.S. Coy.**  
 Port belonging to **Glasgow** Destined Voyage **"**  
 If Surveyed Afloat or in Dry Dock **Dry Dock**

Last Survey, No. **13644** Port of **Dron** Classed **100 A1** 11/4  
 Present Condition of the Decks **Good** **Iron** **Good**  
 Waterways **"** Breasthooks and Stemson **"**  
 Comings **"** Transoms, Pointers, and Crutches **"**  
 Upper Deck Beams & Fastenings **"** ~~Timbers~~ of the Frame at the Openings **"**  
 Lower Deck Beams & Fastenings **"** ~~Ditto~~ ditto at other places **"**  
 Planksheers **Plating** Keelsons **"**  
 Sheerstrakes **"** Clamps and Shelves **"**  
 Topsides **"** Ceiling **"**  
 Wales **"** Rudder **"**  
 (Bottom) and Counter **"** Copper or Y.M. Paint When put on **Now**  
 Caulking of Bottom, Deck, & Waterways **Good**  
 Windlass and Capstan **Good**  
 Pumps **Good**  
 Boats **Good**  
 Masts, Yards, &c. **Sufficient**  
 Condition, how ascertained **where they could be seen**  
 Sails **"**  
 Anchors, No. of **3 B.S.K.**  
 Cables **"**  
 Hawser and Warps **"**  
 Standing and Running Rigging **Good**  
 Engine Room Skylights **Good** Coal Bunker, Openings, Lids, &c. **Good** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**  
 General Observations, Opinion as to Class, &c. **The vessel placed in the dry dock and bottom scraped painted & coated. The cocks and piping in connection with the machinery have been examined and found to be so arranged that water cannot by accident or neglect be run from the sea into the bilge. She is now in an efficient state of repair and in our opinion eligible to remain as classed.**  
 Committee's Minute **27<sup>th</sup> August 1875** **James Bain**  
 Character assigned **100 A1** Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) **Paid** 18

No. in Reg. Book. **No.** 533 Survey held at **London** Date, first Survey **1872** Last Survey **14<sup>th</sup> Aug 1875**  
 on the **S.S. Sestos** Master **Harris**  
 Tonnage **1196** Built at **Glasgow** When built **1872 - 8<sup>th</sup> mo.**  
 By whom built **Len. & Co. S. Shipbuilders** Owners **Globe S.S. Coy**  
 Port belonging to **London** Destined Voyage **"**  
 If Surveyed Afloat or in Dry Dock **Dry Dock. Pontoon**

Last Survey, No. **13927** Port of **Dron** Classed **100 A1** 1-75  
 Present Condition of the Decks **Good** **Iron** **Good**  
 Waterways **"** Breasthooks and Stemson **"**  
 Comings **"** Transoms, Pointers, and Crutches **"**  
 Upper Deck Beams & Fastenings **"** ~~Timbers~~ of the Frame at the Openings **"**  
 Lower Deck Beams & Fastenings **"** ~~Ditto~~ ditto at other places **"**  
 Planksheers **Plating** Keelsons **"**  
 Sheerstrakes **"** Clamps and Shelves **"**  
 Topsides **"** Ceiling **"**  
 Wales **"** Rudder **"**  
 (Bottom) and Counter **"** Copper or Y.M. Paint When put on **Now**  
 Caulking of Bottom, Deck, & Waterways **Good**  
 Windlass and Capstan **Good**  
 Pumps **Good**  
 Boats **Good**  
 Masts, Yards, &c. **Sufficient**  
 Condition, how ascertained **where they could be seen**  
 Sails **"**  
 Anchors, No. of **3 B.S.K.**  
 Cables **"**  
 Hawser and Warps **"**  
 Standing and Running Rigging **Good**  
 Engine Room Skylights **Good** Coal Bunkers, Openings, Lids, &c. **Good** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**  
 General Observations, Opinion as to Class, &c. **The vessel placed on the pontoon and bottom scraped painted and coated. She is now in an efficient state of repair and eligible to remain as classed.**

Committee's Minute **27<sup>th</sup> August 1875** **James Bain**  
 Character assigned **100 A1** Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) **Paid** 18  
 3000-10/6/74  
 25/8/75

IRON 463-0086

