

ANNUAL SURVEYS.

No. 12903 Survey held at Newcastle Date 8th Sep 18 75
on the S. S. "Gorm" Master Mr T. A. Juhl
Tonnage 1753 Built at Ponfrew When built 1871 9 Mo
By whom built Henderson & Co Owners Carl & Co
Port belonging to Copenhagen Destined Voyage Baltic
If Surveyed Afloat or in Dry Dock Wallsend Patent Slip

Last Survey, No. 14744 Port of Liver Classed 90A1
S. S. Lon R-1.75 6.75
The present Condition of the
Decks Good Treenails Piety Good Windlass and Capstan Good
Waterways do Breasthooks and Stemson do Pumps do
Comings do Transoms, Pointers, and Crutches do Boats do
Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do Masts, Yards, &c. do
Lower Deck Beams & Fastenings do Ditto ditto at other places do Sails do
Planksheers do Keelsons do Anchors, No. of Complete
Sheerstrakes do Clamps and Shelves do Cables Complete
Topsides do Ceiling do Hawesers and Warps Complete
Wales do Rudder do Standing and Running Rigging Good
Plank (Bottom) and Counter do Copper paint When put on now
General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good

Bottom cleaned, and painted. She is now in good and efficient condition, eligible to remain as classed.

Committee's Minute 21st September 18 75

Character assigned 90A1

Certificate (if required).

No. 12903 Survey held at Newcastle Date 8th Sep 18 75
on the S. S. "Serantes" Master Jarvis
Tonnage 470 Built at Sunderland When built 1872 10 Mo
By whom built Simcy Owners Johnson & Co
Port belonging to Newcastle Destined Voyage ✓
If Surveyed Afloat or in Dry Dock Clelands Patent Slip

Last Survey, No. 13821 Port of Newcastle Classed 90A1
12.74
The present Condition of the
Decks Good Treenails Piety Good Windlass and Capstan Good
Waterways do Breasthooks and Stemson do Pumps do
Comings do Transoms, Pointers, and Crutches do Boats do
Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do Masts, Yards, &c. do
Lower Deck Beams & Fastenings do Ditto ditto at other places do Sails do
Planksheers do Keelsons do Anchors, No. of Complete
Sheerstrakes do Clamps and Shelves do Cables Complete
Topsides do Ceiling do Hawesers and Warps Complete
Wales do Rudder do Standing and Running Rigging Good
Plank (Bottom) and Counter do Copper paint When put on now
General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good

Bottom cleaned, and painted. She is now in Good and efficient condition, eligible to remain as classed.

Committee's Minute 21st September 18 75

Character assigned 90A1

Certificate (if required).