

ANNUAL SURVEYS.

15722

Rec'd 4/10/75

No. in Reg. Book. **No. 130** Survey held at **Hamburg** Date, first Survey **Sept** Last Survey **4 October 1875**
 on the **Iron Steamer Imma** Master **Adolph Sasy**
 Tonnage **434** Built at **Newcastle** When built **1862** 9 mo
 By whom built **Leslie** Owners **G. Hagen & Co**
 Port belonging to **Hamburg** Destined Voyage **Tokohama via Cardiff**
 If Surveyed Afloat or in Dry Dock **Patent Slips**

Last Survey, No. **45149** Port of **Newcastle Iron** Classed **100 A T**
 Present Condition of the
 Decks **Repaired & Good** Treenails **Riveting Good**
 Waterways **Good** Breasthooks and Stemson
 Comings **Iron Good** Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings **Good** Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings **Good** Ditto ditto at other places
 Planksheers } **Plating Good** Keelsons **Good**
 Sheerstrakes } **Good** Clamps and Shelves **Good**
 Topsides } **Good** Ceiling **Good**
 Wales } **Good** Rudder **Good**
 Plank (Bottom) and Counter **Good** Copper or Y.M. **Patent When put on**
 Caulking of **Good**
 Bottom, Deck, & Waterways **Good**
 Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
 General Observations, Opinion as to Class, &c.

The vessel is in a very good condition and to remain, 100, A. T.

Committee's Minute **5th October 1875**
 Character assigned **100 A T**
 Surveyor to Lloyd's Register of British and Foreign Shipping
 Certificate (if required) **Emil Paddesatz**
 Paid **£ 1. 6. 0** 18

No. Survey held at Date, first Survey Last Survey 18
 No. in Reg. Book. on the Master
 Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed
 Present Condition of the
 Decks Treenails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Caulking of
 Bottom, Deck, & Waterways
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

Committee's Minute 18
 Character assigned
 Surveyor to Lloyd's Register of British and Foreign Shipping
 Certificate (if required) Paid 18

IRON 463-0114

