

15215
REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. **No. 132** Survey held at **Humbly Grove** Date, first Survey **14 Octbr** Last Survey **18 75**
305 on the **Iron Ship, "Dolbadern Castle"** Master **George Stewart**
TONNAGE under Tonnage Deck **898** Built at **Sunderland** When built **1863** — **11**
Ditto of Spar Deck, or Awning Deck
Ditto of Poop, or Raised Qr. Dk.
Ditto of Houses on Deck
Ditto of Forecastle
Gross Tonnage **989** Owners **Hughes & Co** Port belonging to **Liverpool**
Crew Space, as per Rule
Register Tonnage, out on Beam
Engine Room
Reg. Tons as St' mer, out on Bm. **989** By whom built **Oswald** Destined Voyage **East Indies**
If Surveyed Afloat or in Dry Dock **In a Dry Dock**
Length of Poop **103 00** ft. Ditto, Forecastle **15 00** ft. Ditto, Raised Quarter Deck **15 00** ft. Years assigned. **8 72** Character in Register Book. *** A 1**
Last Survey, No. **48593** Port **S.S. Liverpool No 2-12** Classed **8 72**
REPAIRS, OR EXAMINATION AS PER RULE

Bottom sighted & examined & found in a very good condition & also the riveting coated with patent paint. The cement clear of all chafe & sound, also found that the Lower Hold, Iron Peak, Mast & Tanks had been all well chipped and painted.

Present Condition of the				
Decks	Good	Greenails	Rivets	Good
Waterways	"	Breasthooks and Stemson		
Comings	"	Transoms, Pointers, and Crutches		
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings		
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places		
Planksheers	"	Keelsons		
Sheerstrakes	"	Clamps and Shelves		
Topsides	"	Ceiling		
Wales	"	Rudder		
Plank (Bottom) and Counter	"	Copper Painted When put on	Now	
Engine Room Skylights		Caulking of		
Coal Bunker, Openings, Lids, &c.		Bottom, Deck, & Waterways		
General Observations, Opinion as to Class, &c.		Windlass and Capstan	Good	
		Pumps	"	
		Boats	"	
		Masts, Yards, &c.	"	
		Condition, how ascertained	"	
		Sails	"	
		Anchors No. of	"	
		Cables	"	
		Hawsers and Warps	"	
		Standing & Running Rigging	Partly new	
		Good Cargo and Main Hatchways	Good	
		Hatches	Good	

The vessel having undergone ~~overhaul~~ a good overhaul is fit in my opinion to remain *** A 1**

The Amount of Entry Fee ... £ 1 : 0 : 0 received by me, }
Special ... £ 1 : 0 : 0 187 }
Certificate (if required) ... £ 0 : 5 : 0
(Travelling Expenses, if any, £ 3 0 0)

Committee's Minute **22nd October** 18 **75**

Character assigned

Emil Poddert
Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019
Lloyd's Register
Foundation

IRON 63-0254