

ANNUAL SURVEYS.

15282

35.071

No. in Reg. Book. **271** No. **13578** Survey held at London Date, first Survey Sept 16 Last Survey 1875
 on the S Persian Empire Master Suncanbo
 Tonnage 1532 Built at W Hartlepool When built 1865 9M
 By whom built Pile Owners Suncanbo
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 13578 Port of London Classed A1 Years assigned 11-74 Character in Register Book. SS Lin M2-74
 Present Condition of the Decks Good
 Waterways Good Breasthooks and Stemson Good
 Comings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
 Planksheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shelves Good
 Topsides Good Ceiling Good
 Wales Good Rudder Good
 Plank (Bottom) and Counter Good Copper or Y.M. Painted When put on Non
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom Scraped Painted & Part new bulwark & Planks coated where exposed. She is now in an efficient state of repair and in my opinion entitled to remain as classed.

Committee's Minute 28th September 1875 Senhouse Martindale
 Character assigned T.D.W. Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. in Reg. Book. **881** No. **12925** Survey held at London Date, first Survey Aug 27 Last Survey 1875
 on the S Coldingham Master Willis Wan
 Tonnage 1055 Built at Liverpool When built 1866 1M
 By whom built Hart Owners Willis Wan
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 12925 Port of London Classed A1 Years assigned 6-74 Character in Register Book. SS Lin M1-72
 Present Condition of the Decks Good
 Waterways Good Breasthooks and Stemson Good
 Comings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
 Planksheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shelves Good
 Topsides Good Ceiling Good
 Wales Good Rudder Good
 Plank (Bottom) and Counter Good Copper or Y.M. Painted When put on Non
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom Scraped Painted &c. She is now in an efficient state of repair and in my opinion entitled to remain as classed.

Committee's Minute 28th September 1875 Senhouse Martindale
 Character assigned T.D.W. Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18