

# ANNUAL SURVEYS.

15283

25022

No. in Reg. Book. **No.** 325 on the **SS Henry Morton** Survey held at **London** Date, first Survey **Sept 21<sup>st</sup> 1875** Last Survey **Sept 21<sup>st</sup> 1875**  
 Tonnage **286** Built at **Newcastle** When built **1860 10 mo**  
 By whom built **Palmer** Owners **Cory & Co**  
 Port belonging to **London** Destined Voyage   
 If Surveyed Afloat or in Dry Dock **Pontoon**

Last Survey, No. **13259** Port of **Iran**

Present Condition of the Decks **Good**

Classed **A1** Years assigned **3.74** Character in Register Book **SS Lon W 2-74**

Waterways	Good	Treenails	Rivets	Good	Windlass and Capstan	
Comings	"	Breasthooks and Stemson		"	Pumps	
Upper Deck Beams & Fastenings	"	Transoms, Pointers, and Crutches		"	Boats	
Lower Deck Beams & Fastenings	"	Timbers of the Frame at the Openings		"	Masts, Yards, &c.	Good
Planksheers	"	Ditto ditto at other places	"	"	Condition, how ascertained	and
Sheerstrakes	"	Keelsons	"	"	Sails	Sufficient
Topsides	"	Clamps and Shelves	"	"	Anchors, No. of <b>3 B's. 12 1/2</b>	where
Wales	"	Ceiling	"	"	Cables	they could be seen
Plank (Bottom) and Counter	"	Rudder	"	"	Hawsers and Warps	
Engine Room Skylights	Good	Copper or Y.M. Painted When put on <b>Now</b>		"	Standing and Running Rigging	
Coal Bunker, Openings, Lids, &c.	Good	Caulking of Bottom, Deck, & Waterways	Good	"		
General Observations, Opinion as to Class, &c.	Bottom Scraped Painted & Coated					

She is now in an efficient state of repair and enabled to remain as classed

Senhouse Martindale

Committee's Minute **8<sup>th</sup> October 1876**

Character assigned **A1**

Surveyor to Lloyd's Register of British and Foreign Shipping. Certificate (if required) Paid 18

No. in Reg. Book. **No.** 296 on the **S Peterborough** Survey held at **London** Date, first Survey  Last Survey **Aug 28 1875**  
 Tonnage **1680** Built at **Stockton** When built **1874 4**  
 By whom built **Richardson** Owners **Merchant Shipping Co**  
 Port belonging to **London** Destined Voyage   
 If Surveyed Afloat or in Dry Dock **Dry Dock**

Last Survey, No. **12769** Port of **born**

Classed **100A1** Years assigned **5.74** Character in Register Book

Waterways	Good	Treenails	Rivets	Good	Windlass and Capstan	
Comings	"	Breasthooks and Stemson		"	Pumps	
Upper Deck Beams & Fastenings	"	Transoms, Pointers, and Crutches		"	Boats	
Lower Deck Beams & Fastenings	"	Timbers of the Frame at the Openings		"	Masts, Yards, &c.	Good
Planksheers	"	Ditto ditto at other places	"	"	Condition, how ascertained	and
Sheerstrakes	"	Keelsons	"	"	Sails	Sufficient
Topsides	"	Clamps and Shelves	"	"	Anchors, No. of <b>3 B's. 12 1/2</b>	where
Wales	"	Ceiling	"	"	Cables	they could be seen
Plank (Bottom) and Counter	"	Rudder	"	"	Hawsers and Warps	
Engine Room Skylights	Good	Copper or Y.M. Painted When put on <b>Now</b>		"	Standing and Running Rigging	
Coal Bunkers, Openings, Lids, &c.	Good	Caulking of Bottom, Deck, & Waterways	Good	"		
General Observations, Opinion as to Class, &c.	At present Bottom Scraped Painted &c.					

She is now in an efficient state of repair and enabled to remain as classed

Senhouse Martindale

Committee's Minute **8<sup>th</sup> October 1875**

Character assigned **100A1**

Surveyor to Lloyd's Register of British and Foreign Shipping. Certificate (if required) Paid 18



© 2019

Lloyd's Register Foundation

IRON463-0366