

ANNUAL SURVEYS.

No. 24821 Survey held at Liverpool Date Oct 5th 1875
 on the (Iron) "Whersonese" Master J. Ellison
 Tonnage 1711 Built at Belfast When built 1855
 By whom built 1611 Owners G. Duncan
 Port belonging to London Destined Voyage India
 If Surveyed Afloat or in Dry Dock Herculanian graving dock

Last Survey, No. 13265 Port of London Classed 100 A 1 74
1st Div. No 3-74

The present Condition of the

Decks	<u>Good</u>	Trunnels	<u>Rivets</u>	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	"	Breasthooks and Stems	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	<u>Not seen</u>	"	Sails	<u>and</u>
Planksheers	"	Keelsons	<u>Not seen</u>	<u>Good</u>	Anchors, No. of	"
Sheerstrakes	"	Clamps and Shelves	"	"	Cables	"
Topsides	"	Ceiling	"	"	Hawsers and Warps	"
Wales	"	Rudder	"	"	Standing and Running Rigging	<u>Efficient</u>
Plates (Bottom) and Counter	"	Copper	<u>Cem</u>	When put on <u>74</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

The bottom scraped and painted. Is now in good condition and in my opinion eligible to remain as Classed.

Committee's Minute Liverpool, 26th October, 1875

Character assigned 100 A 1
882

E. B. Wheeler

Certificate (if required).

No. 261 Survey held at Liverpool Date Oct 15th 1875
 on the (Iron) "Luke Bruce" Master Bell
 Tonnage 320 Built at Aberdeen When built 1868 - 11 mo
 By whom built Hall Russell & Co Owners Harrison & Co
 Port belonging to Liverpool Destined Voyage Africa
 If Surveyed Afloat or in Dry Dock Afloat in Herculanian graving dock

Last Survey, No. 114369 Port of London Classed * A 1
1st Div. No 1-72
75

The present Condition of the

Decks	<u>Good</u>	Trunnels	<u>Rivets</u>	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	"	Breasthooks and Stems	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	<u>Not seen</u>	"	Sails	<u>and</u>
Planksheers	"	Keelsons	"	<u>Good</u>	Anchors, No. of	"
Sheerstrakes	<u>Good</u>	Clamps and Shelves	"	"	Cables	"
Topsides	"	Ceiling	"	"	Hawsers and Warps	<u>efficient</u>
Wales	"	Rudder	"	"	Standing and Running Rigging	"
Plates (Bottom) and Counter	"	Copper	<u>Cem</u>	When put on <u>68</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

The bottom scraped and painted. Is now in good condition and in my opinion eligible to remain as Classed.

Committee's Minute Liverpool, 26th October, 1875

Character assigned * A 1
882

E. B. Wheeler

Certificate (if required).