

# ANNUAL SURVEYS.

No. in Reg. Book. **No.** 28 Survey held at London Date, first Survey 1874 Last Survey Sept 20 1874  
 on the S Carnaby Master W. J. White  
 Tonnage 1567 Built at Aberdeen When built 1874 3 mo.  
 By whom built J. White Owners W. J. White  
 Port belonging to Aberdeen Destined Voyage   
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 12780 Port of Iron Classed 100A 5.74  
 Present Condition of the Decks Good  
 Waterways Good Breasthooks and Stemson Good  
 Comings Good Transoms, Pointers, and Crutches Good  
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good  
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good  
 Planksheers Good Keelsons Good  
 Sheerstrakes Good Clamps and Shelves Good  
 Topsides Good Ceiling Good  
 Wales Good Rudder Good  
 Plank (Bottom) and Counter Good Copper or Y.M. Painted When put on Now  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c.

The Bottom Scraped Painted & Coated  
 She is now in an efficient state of repair and entitled to remain as classed

Committee's Minute 8th October 1875 Senhouse Martindale  
 Character assigned 100A J. White Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18

No. in Reg. Book. **No.** 786 Survey held at London Date, first Survey 1875 Last Survey Augt 26 1875  
 on the S Louisa Master Adams  
 Tonnage 1304 Built at Or Glasgow When built 1864 11 mo.  
 By whom built Reed Owners Shaw Savill & Co.  
 Port belonging to London Destined Voyage   
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 13068 Port of Iron Classed 100A 18.74  
 Present Condition of the Decks Good  
 Waterways Good Breasthooks and Stemson Good  
 Comings Good Transoms, Pointers, and Crutches Good  
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good  
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good  
 Planksheers Good Keelsons Good  
 Sheerstrakes Good Clamps and Shelves Good  
 Topsides Good Ceiling Good  
 Wales Good Rudder Good  
 Plank (Bottom) and Counter Good Copper or Y.M. Painted When put on Now  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c.

The Bottom Scraped Painted & Coated  
 She is now in an efficient state of repair and entitled to remain as classed

Committee's Minute 8th October 1875 Senhouse Martindale  
 Character assigned 100A J. White Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18