

ANNUAL SURVEYS.

No. in Reg. Book. on the No. 13017 Survey held at Newcastle Date, first Survey 18th Sep Last Survey 10th Sep 1875.
290 Tonnage 576 Built at Newcastle When built 1873 3 Mo
 By whom built Palmer & Co Owners Northfleet Coal & Ball Co
 Port belonging to London Destined Voyage Coasting
 X Surveyed Afloat or in Dry Dock Cleland's Patent Ship

Last Survey, No. 12284 Port of Newcastle Iron Classed 80 A 1
 Present Condition of the Decks Good 5.73
 Waterways do Breasthooks and Stemson do
 Comings do Transoms, Pointers, and Crutches do
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do
 Lower Deck Beams & Fastenings do Ditto ditto at other places do
 Planksheers do Keelsons do
 Sheerstrakes do Clamps and Shelves do
 Topsides do Ceiling do
 Wales do Rudder do
 Plank (Bottom) and Counter do Copper on Y.M. Paint When put on Now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, & Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Renewed some rivets in the landing edges of the Plating. Bottom cleaned and Painted. She is now in Good and Efficient condition, eligible to remain as classed.

Committee's Minute 26th October 1875
 Character assigned 80 A 1 TRW
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. in Reg. Book. on the No. 13017 Survey held at Newcastle Date, first Survey 12th Oct Last Survey 12th Oct 1875.
632 Tonnage 1025 Built at Kiel When built 1873 1 Mo
 By whom built N. Grym Owners Copenhagen Steam Sh. Co
 Port belonging to Copenhagen Destined Voyage Copenhagen
 X Surveyed Afloat or in Dry Dock Wallsend Patent Ship

Last Survey, No. 13018 Port of Iron Classed 90 A 1
 Present Condition of the Decks Good 7.74
 Waterways do Breasthooks and Stemson do
 Comings do Transoms, Pointers and Crutches do
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do
 Lower Deck Beams & Fastenings do Ditto ditto at other places do
 Planksheers do Keelsons do
 Sheerstrakes do Clamps and Shelves do
 Topsides do Ceiling do
 Wales do Copper on Y.M. Paint When put on Now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, & Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom cleaned, and painted. She is now in Good & Efficient condition, eligible to remain as classed.

Committee's Minute 26th October 1875
 Character assigned 90 A 1 TRW
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18