

ANNUAL SURVEYS.

No. 15453 Survey held at London Date, first Survey Oct^r 14th Last Survey 16th Recd 10.11.75
 in Book. on the Iron Screw Sm^r Princeps Master C. R. Frost 1875
 Tonnage 945.1184 Built at Hull When built 1869 10 ma
 By whom built 969 Owners W. Liddell
 Port belonging to London Hull Destined Voyage Triest
 If Surveyed Afloat or in Dry Dock Mill wall dry dock

Last Survey, No. 14333 Port of Iron Classed A.1. Years assigned 4.75 Character in Register Book S.S. no 3/75
 Present Condition of the
 Rivets good Treenails where seen good
 Breasthooks and Stemson "
 Transoms, Pointers, and Crutches "
 Timbers of the Frame at the Openings "
 Ditto ditto at other places "
 Keelsons "
 Clamps and Shelves "
 Ceiling "
 Rudder efficient "
 Copper or F.M. " When put on "
 Caulking of good
 Bottom, Deck, & Waterways good
 Windlass and Capstan in good order
 Pumps "
 Boats "
 Masts, Yards, &c. "
 Condition, how ascertained from the Deck "
 Sails "
 Anchors, No. of 3 B. 1 S. 2 K "
 Cables "
 Hawesers and Warps "
 Standing and Running Rigging "
 Engine Room Skylights good Coal Bunker, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c.

Recoated the bottom. gave her a new main boom.
Mopuller refitted. - She is in good condition and in my opinion
is entitled to remain as class'd A.1.
Samuel Presius

Committee's Minute 19th November 1875
 Character assigned A.1 TRW

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. 15453 Survey held at London Date, first Survey 21st Oct^r Last Survey 29th Oct^r 1875
 in Book. on the Iron Screw Sm^r Fairfax Master G. Loudon
 Tonnage 709.930.765 Built at Glasgow When built 1865 6 ma
 By whom built Lon^r V Glasgow Comp^y Owners G. I. Screw Collier Comp^y
 Port belonging to London Destined Voyage Shields
 If Surveyed Afloat or in Dry Dock Com^e dry dock

Last Survey, No. 90A.1. Port of Shields Classed 90A.1. Years assigned 3.75 Character in Register Book S.S. no 3/75
 Present Condition of the
 Rivets good Treenails where seen good
 Breasthooks and Stemson "
 Transoms, Pointers, and Crutches "
 Timbers of the Frame at the Openings "
 Ditto ditto at other places "
 Keelsons "
 Clamps and Shelves "
 Ceiling "
 Rudder efficient "
 Copper or F.M. " When put on "
 Caulking of good
 Bottom, Deck, & Waterways good
 Windlass and Capstan in good order
 Pumps "
 Boats "
 Masts, Yards, &c. "
 Condition, how ascertained from the Deck "
 Sails "
 Anchors, No. of 3 B. 1 S. 2 K "
 Cables "
 Hawesers and Warps "
 Standing and Running Rigging "
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c.

Cleaned the bottom, and recoated it, repaired the hatches, and made
good the Canvas of Deck. -
She is in good condition and in my opinion
is entitled to remain as class'd 90A.1.
Samuel Presius

Committee's Minute 19th November 1875
 Character assigned 90A.1 TRW

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

Lloyd's Register
 180464-0106

Papers
of
F. M. J. J. J.



© 2019

Lloyd's Register
Foundation