

15456
ANNUAL SURVEYS.

Rev 22/11/74

No. 3540 Survey held at West Hartlepool Date 8th Nov 18 75
on the Scout "Posa Mary" Master Webster
Tonnage 1221 Built at Hartlepool When built 1875 - 4 mo
By whom built W Gray & Co Owners Lawrence & Co
Port belonging to Hartlepool Destined Voyage _____
If Surveyed Afloat or in Dry Dock In Dry Dock

Last Survey, No. _____ Port of _____ Classed 90 A1
6-75

The present Condition of the

Decks Good
Waterways (Gutter) Good
Comings Good
Upper Deck Beams & Fastenings Good
Lower Deck Beams & Fastenings Good
Planksheers _____
Sheerstrakes Good
Topsides Good
Wales Good
Plank (Bottom) and Counter Good

Treenails Pinch Good
Breasthooks and Stemson Good
Transoms, Pointers, and Crutches Good
Timbers of the Frame at the Openings Good
Ditto ditto at other places Good
Keelsons Good where seen
Clamps and Shelves _____
Ceiling Good
Rudder Good
Copper _____ When put on _____

Windlass and Capstan Good
Pumps 3 & Good
Boats 4 & Good
Masts, Yards, &c. Good
Sails Good
Anchors, No. of 3 Bowers 1 Stream 2 1/2 lbs
Cables Good & Sufficient
Hawsers and Warps 10 7/2 - 7. 5 1/2 - 5 1/2 Good
Standing and Running Rigging Good

General Observations and Opinion,

Now done, bottom cleaned down & boards with paint & black varnish.
Is now in a good & efficient state fit for the safe conveyance of dry &
perishable goods to & from all parts of the World & may in my opinion remain so
now Classed 90 A1

Committee's Minute 23rd November 1875

Character assigned 90 A1 IBW S. P. Gladstone

Certificate (if required).

No. _____ Survey held at _____ Date _____ 18 _____
on the _____ Master _____
Tonnage _____ Built at _____ When built _____
By whom built _____ Owners _____
Port belonging to _____ Destined Voyage _____
If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks _____
Waterways _____
Comings _____
Upper Deck Beams & Fastenings _____
Lower Deck Beams & Fastenings _____
Planksheers _____
Sheerstrakes _____
Topsides _____
Wales _____
Plank (Bottom) and Counter _____

Treenails _____
Breasthooks and Stemson _____
Transoms, Pointers, and Crutches _____
Timbers of the Frame at the Openings _____
Ditto ditto at other places _____
Keelsons _____
Clamps and Shelves _____
Ceiling _____
Rudder _____
Copper _____ When put on _____

Windlass and Capstan _____
Pumps _____
Boats _____
Masts, Yards, &c. _____
Sails _____
Anchors, No. of _____
Cables _____
Hawsers and Warps _____
Standing and Running Rigging _____

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways _____

Committee's Minute _____ 18 _____

Character assigned _____



© 2019

Lloyd's Register Foundation
Certificate (if required).

120N 464-0107