

ANNUAL SURVEYS.

Iron
 No. 24888 Survey held at Liverpool Date, first Survey Nov 4th Last Survey Nov 5th 1875
 Reg. Book. on the Ship "Baroda" Master T. Tully
 Tonnage 1364 Built at Belfast When built 1864 - 4 mo.
 By whom built Harland Owners Brocklebank
 Port belonging to Liverpool Destined Voyage
 If Surveyed Afloat or in Dry Dock Princes Dry Dock

Last Survey, No. 10634 Port of Iron Classed S.S. Liv No 272 Years assigned. 9-72 Character in Register Book. *A1
 Present Condition of the Decks Good Treenails Good Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Paint When put on Now
 Engine Room Skylights ✓ Coal Bunker, Openings, Lids, &c. ✓ Caulking of Bottom, Deck, & Waterways Good
 General Observations, Opinion as to Class, &c. Scuppers Good Cargo and Main Hatchways Good Hatches Good

The bottom sighted, cleaned, and coated with McAlmes Composition, the vessel is now in a good & efficient condition, eligible in my opinion to remain as Classed.

Committee's Minute Liverpool, 10th December 1875 T. Skilston
 Character assigned A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. 546 Survey held at Liverpool Date, first Survey Nov 11th Last Survey Nov 12th 1875
 Reg. Book. on the Bark "Lock Bee" Master Major
 Tonnage 700 Built at P. Glsq. When built 1870 - 3 mo.
 By whom built McElch Owners D & J Sproat
 Port belonging to Liverpool Destined Voyage
 If Surveyed Afloat or in Dry Dock Princes Dry Dock

Last Survey, No. 13021 Port of Iron Classed S.S. Liv No 174 Years assigned. 7-74 Character in Register Book. *A1
 Present Condition of the Decks Good Treenails Good Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Paint When put on Now
 Engine Room Skylights ✓ Coal Bunkers, Openings, Lids, &c. ✓ Caulking of Bottom, Deck, & Waterways Good
 General Observations, Opinion as to Class, &c. Scuppers Good Cargo and Main Hatchways Good Hatches Good

Bottom sighted, cleaned and coated with paint the vessel is now in a good and efficient condition, eligible in my opinion to remain as classed.

Committee's Minute Liverpool, 10th December 1875 T. Skilston
 Character assigned A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

"Lock We

24888



"Barreda

©2019

Lloyd's Register
Foundation