

ANNUAL SURVEYS.

No. in Reg. Book. on the **No. 24855** Survey held at **Liverpool** Date, first Survey **Oct 21** Last Survey **Nov 3** 18**75**
334 on the **(Iron) "Ivanhoe"** Master **H Lurke**
 Tonnage **1303** Built at **Glasgow** When built **1868 - 10 mo**
 By whom built **Reed** Owners **Williamson & Co**
 Port belonging to **Liverpool** Destined Voyage **India**
 If Surveyed Afloat or in Dry Dock **Afloat in Queen's graving dock**

Last Survey, No. **11917** Port of **Liverpool**
 Present Condition of the Decks **Good**
 Waterways **"**
 Comings **"**
 Upper Deck Beams & Fastenings **"**
 Lower Deck Beams & Fastenings **"**
 Planksheers **"**
 Sheerstrakes **"**
 Sides **"**
 (Bottom) and Counter **"**
 Skylights **"**
 Coal Bunker, Openings, Lids, &c. **"**
 Observations, Opinion as to Class, &c. **The bottom scraped and painted - Is now in good condition and in my opinion eligible to remain as Classed -**

Treenails **Perish - Good**
 Breasthooks and Stems **"**
 Transoms, Pointers, and Crutches **"**
 Timbers of the Frame at the Openings **"**
 Ditto ditto at other places **Not seen**
 Keelsons **Good**
 Clamps and Shelves **"**
 Ceiling **"**
 Rudder **"**
 Copper or Y.M. Cam When put on **68**
 Caulking of Bottom, Deck, & Waterways **Good**
 Scuppers **Good**
 Cargo and Main Hatchways **Good**
 Hatches **Good**

Windlass and Capstan **Good & efficient**
 Pumps **"**
 Boats **"**
 Masts, Yards, &c. **"**
 Condition, how ascertained **Seen from deck**
 Sails **Good**
 Anchors, No. of **"**
 Cables **and**
 Hawser and Warps **"**
 Standing and Running Rigging **efficient**

Committee's Minute **Liverpool 19th November 1875**
 Character assigned **A**

E. C. Wheeler
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) **"** Paid **18**

No. in Reg. Book. on the **No. 997** Survey held at **Liverpool** Date, first Survey **Oct 7** Last Survey **Oct 12** 18**75**
997 on the **(Iron) "Brady Maid"** Master **Harmond**
 Tonnage **837** Built at **Glasgow** When built **1868 - 10 mo**
 By whom built **Steele** Owners **Thompson & Co**
 Port belonging to **Leith** Destined Voyage **Bangor**
 If Surveyed Afloat or in Dry Dock **Afloat in Queen's graving dock**

Last Survey, No. **13206** Port of **Liverpool**
 Present Condition of the Decks **Good**
 Waterways **"**
 Comings **"**
 Upper Deck Beams & Fastenings **"**
 Lower Deck Beams & Fastenings **"**
 Planksheers **"**
 Sheerstrakes **"**
 Sides **"**
 (Bottom) and Counter **"**
 Skylights **"**
 Coal Bunkers, Openings, Lids, &c. **"**
 Observations, Opinion as to Class, &c. **The bottom scraped & painted. Is now in good condition and in my opinion eligible to remain as Classed -**

Treenails **Perish - Good**
 Breasthooks and Stems **"**
 Transoms, Pointers, and Crutches **"**
 Timbers of the Frame at the Openings **"**
 Ditto ditto at other places **Not seen**
 Keelsons **"**
 Clamps and Shelves **"**
 Ceiling **Good**
 Rudder **"**
 Copper or Y.M. Cam When put on **68**
 Caulking of Bottom, Deck, & Waterways **Good**
 Scuppers **Good**
 Cargo and Main Hatchways **Good**
 Hatches **Good**

Windlass and Capstan **Good & efficient**
 Pumps **"**
 Boats **"**
 Masts, Yards, &c. **"**
 Condition, how ascertained **Seen from deck**
 Sails **Good**
 Anchors, No. of **"**
 Cables **and**
 Hawser and Warps **"**
 Standing and Running Rigging **efficient**

Committee's Minute **Liverpool 19th November 1875**
 Character assigned **A**

E. C. Wheeler
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) **"** Paid **18**

120N464-0153

ANNUAL SURVEYS

211

1850

"
Shady Mount
"

24850

"
Shamhor
"