

No.            Survey held at London Date, first Survey            Last Survey Nov 26 1875  
No. in Reg. Book. on the S Saint Marnock Master 15512  
91 Tonnage 1258 Built at Liverpool When built 1867 SM  
By whom built Royden Owners Rankin & Co.  
Port belonging to Glasgow Destined Voyage             
If Surveyed Afloat or in Dry Dock Pontoon

Last Survey, No. 13594 Port of Iron Classed Years assigned. A 7 Character in Register Book. 11.74  
Present Condition of the Decks Good Treenails Good Rivets Good  
Waterways            Breasthooks and Stemson             
                     Transoms, Pointers, and Crutches             
                     Timbers of the Frame at the Openings             
Upper Deck Beams & Fastenings            Ditto ditto at other places             
Lower Deck Beams & Fastenings            Keelsons             
                     Clamps and Shelves             
Sheerstrakes            Ceiling             
Topsides            Rudder             
Wales            ~~Copper or F.M.~~ Painted When put on Now  
Plank (Bottom) and Counter            Caulking of Bottom, Deck, & Waterways Good  
Engine Room Skylights            Coal Bunkers, Openings, Lids, &c.            Scuppers Good Cargo and Main Hatchways Good Hatches Good  
General Observations, Opinion as to Class, &c.           

*She is now in an efficient state of repair and respectfully recommends her to remain as classed*

Committee's Minute 3<sup>rd</sup> December 1875 Leithhouse Martindale  
Character assigned            Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)            Paid            18