15540 33,169

REPORT of SURVEY for REPAIRS, &c.

(Rec. 13.12.75)

in Book. **No.** 165 Survey held at London Date, first Survey Nov 22 Last Survey Dec 11 16.12.75 1875

on the S Mercantile Francis Master Bidwell

TONNAGE under Tonnage Deck	1075	Built at	P Glasgow	When built	YEAR. 1863 MONTH. 5
Ditto of Spar Deck, or Awning Deck		Owners	Johnston & Co	Port belonging to	Liverpool
Ditto of Poop, or Raised Qr. Dk.		Residence			
Ditto of Houses on Deck		By whom built	Reid	Destined Voyage	New Zealand
Ditto of Forecastle		If Surveyed Afloat or in Dry Dock	afloat		
Gross Tonnage					
Crew Space, as per Rule					
Register Tonnage, cut on Beam					
Engine Room					
Reg. Tons as St'mer, cut on Bm.					

Official Number

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft.

Last Survey, No. 11204 (4430) **Port** Iron (Hull)

Classed Years assigned. X A 1 — Character in Register Book. 3.73 — 88 Jun M 2.71

REPAIRS, OR EXAMINATION AS PER RULE

At the present time in compliance with the attached letter from the Societys Surveyor at Hull the 'tween decks have been cleaned and Painted many of the bolts in the Main deck have been removed with through Screw bolts & nuts and others Screwed up solid.

The Rigging is all complete & the following Ropes &c are on board

Viz 1 Coir line 12 Inches Nearly New
" 9 Inches In use some time will pro
7 " Good
5 " New. also 4 hauling lines
a Good Stream Chain.
3 Bs anchors a Stream & 2 Kedges & 4 Boats

Present Condition of the Decks	Good where seen	Treenails	Rivets	Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	Good and sufficient where they could be seen
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelfs	Good where seen	Anchors No. of 3 Bs 2 Kedges	
Topsides		Ceiling		Cables	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Copper When put on		Standing & Running Rigging	
Engine Room Skylights —	Coal Bunker, Openings, Lids, &c. —		Caulking of Bottom, Deck, & Waterways	Scuppers Good	Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c.

She appears in an efficient state of repair and respectfully submit that she may be classed as recommended by the Societys Surveyor at Hull

Lenhouse Martindale

The Amount of Entry Fee ... ...£ — : — :
Special ... ...£ 1 : 1 :
Certificate (if required) ... ...£ — : — :
(Travelling Expenses, if any, £)

received by me, [illegible] 16/12 1875

Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute 14th December 1875

Character assigned [illegible] S.S. No 3-75

Before me Hull Surveyor 17.12.75

(The Surveyors are requested not to write on or below the space for Committee's Minute.)

[3,000—8/3/75.]

© 2019 Lloyd's Register Foundation

IRON464-0214