

No. 41 Survey held at Calcutta 15546 Date 17<sup>th</sup> November 1875  
64 on the ship Pandora Master John Robb.  
 Tonnage 1156 Built at Glasgow When built 1864 - 3 mo  
 By whom built Charles Connell Owners Jansbath & Timmer  
 Port belonging to Liverpool Destined Voyage West Indies  
 If Surveyed Afloat or in Dry Dock afloat

Last Survey, No. 12936 Port of Liverpool Lion Classed \*A1

The present Condition of the

Decks <u>good where seen</u>	Treenails <u>Rivetting good where seen</u>	Windlass and Capstan <u>good order</u>
Waterways <u>guttering do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>good condition</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>6 all sound</u>
Upper Deck Beams & Fastenings <u>do</u>	<del>Timbers</del> of the Frame at the Openings <u>do</u>	Masts, Yards, &c. <u>all good</u>
Lower Deck Beams & Fastenings <u>do</u>	<del>Ditto</del> ditto at other places <u>do</u>	Sails <u>2 suits (good)</u>
Planksheers <u>plating do</u>	Keelsons <u>do</u>	Anchors, No. of <u>3 Bowers, 1 stream, 2 Kedges</u>
Sheerstrakes <u>do do</u>	Clamps and Shelves <u>do</u>	Cables <u>150 fms (w) chain, (2 bowers) 60 fms stream</u>
Topsides <u>do do</u>	Ceiling <u>do</u>	Hawsers and Warps <u>6 assorted sizes</u>
Wales <u>do do</u>	Rudder <u>good &amp; well hung</u>	Standing and Running Rigging <u>all good</u>
Planks <u>not seen outside</u> (Bottom) and Counter <u>do</u>	Copper Paint When put on <u>June 1875</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways new

A strong well built iron ship, has been well kept and is in my opinion fit to be retained on the Register as classed -

Committee's Minute 31<sup>st</sup> December 1875

Character assigned T.B.W.

W Stewart

Surveyor to Lloyd's Register of B. & F. Shipping  
 Port of Calcutta  
26<sup>th</sup> Nov 75  
 Certificate (if required).