

# ANNUAL SURVEYS.

14/12/75  
15554  
No. 24901 Survey held at Liverpool Date, first Survey Nov 16<sup>th</sup> Last Survey Nov 17<sup>th</sup> 1875  
Reg. Book. on the Ship "Victoria Nyamoa" Master Lodge  
180 Tonnage 1022 Built at Belfast When built 1863 - 8 mo.  
By whom built Harland Owners G. Fletcher.  
Port belonging to Liverpool Destined Voyage San Francisco.  
If Surveyed Afloat or in Dry Dock Canning Dry Dock.

Last Survey, No. 13560 Port of Iron Classed S.S. Liv. No 3-74 10-74  
Present Condition of the Decks Good  
Waterways "  
Comings "  
Upper Deck Beams & Fastenings "  
Lower Deck Beams & Fastenings "  
Planksheers "  
Sheerstrakes "  
Topsides "  
Wales "  
Plank (Bottom) and Counter "  
Engine Room Skylights ✓ Coal Bunker, Openings, Lids, &c. ✓ Scuppers Good Cargo and Main Hatchways Good Hatches Good  
General Observations, Opinion as to Class, &c.  
Breasthooks and Stimson Good  
Transoms, Pointers, and Crutches "  
Timbers of the Frame at the Openings "  
Ditto ditto at other places "  
Keelsons "  
Clamps and Shells "  
Ceiling "  
Rudder "  
Copper or Y.M. Paint When put on Now  
Caulking of Bottom, Deck, & Waterways Good  
Windlass and Capstan Good  
Pumps 2 in No  
Boats 4 in No  
Masts, Yards, &c. "  
Condition, how ascertained from on board  
Sails Good  
Anchors, No. of 3 B - 1 S - 2 K  
Cables part seen Good  
Hawsers and Warps and  
Standing and Running Rigging Sufficient

Committee's Minute Liverpool 17<sup>th</sup> December 1875 J. Shilston  
Character assigned A Surveyor to Lloyd's Register of British and Foreign Shipping.  
Certificate (if required) ✓ Paid 18

No. 535 Survey held at Liverpool Date, first Survey Nov 16<sup>th</sup> Last Survey Nov 16<sup>th</sup> 1875  
Reg. Book. on the Bark "Prince Arthur" Master Jeffrey  
535 Tonnage 544 Built at Liverpool When built 1864 - 5 mo.  
By whom built Vernon Owners Nelson & Co.  
Port belonging to Liverpool Destined Voyage Not fixed.  
If Surveyed Afloat or in Dry Dock Princes Dry Dock

Last Survey, No. 12134 Port of Iron Classed S.S. No 2-72 12-73.  
Present Condition of the Decks Good  
Waterways "  
Comings "  
Upper Deck Beams & Fastenings "  
Lower Deck Beams & Fastenings "  
Planksheers "  
Sheerstrakes "  
Topsides "  
Wales "  
Plank (Bottom) and Counter "  
Engine Room Skylights ✓ Coal Bunkers, Openings, Lids, &c. ✓ Scuppers Good Cargo and Main Hatchways Good Hatches Good  
General Observations, Opinion as to Class, &c.  
Breasthooks and Stimson Good  
Transoms, Pointers, and Crutches "  
Timbers of the Frame at the Openings "  
Ditto ditto at other places "  
Keelsons "  
Clamps and Shells "  
Ceiling "  
Rudder "  
Copper or Y.M. Paint When put on Now  
Caulking of Bottom, Deck, & Waterways Good  
Windlass and Capstan Good  
Pumps "  
Boats "  
Masts, Yards, &c. "  
Condition, how ascertained from on board  
Sails Good  
Anchors, No. of "  
Cables and  
Hawsers and Warps Sufficient  
Standing and Running Rigging Good

Committee's Minute Liverpool 17<sup>th</sup> December 1875 J. Shilston  
Character assigned A Surveyor to Lloyd's Register of British and Foreign Shipping.  
Certificate (if required) ✓ Paid 18



Lloyd's Register  
Foundation