

# ANNUAL SURVEYS.

No. in Reg. Book. on the **No 24920** Survey held at **Birkhead** Date, first Survey **7th Decr** Last Survey **9th December 1875**  
**S.S. "Dante"** Master **Buchanan**  
 Tonnage **1133** Built at **S. Shields** When built **1874-5 mo**  
 By whom built **Softley** Owners **Glover Brothers. London**  
 Port belonging to **London** Destined Voyage **Bombay**  
 If Surveyed Afloat or in Dry Dock **Glover & Clayton's G. St**

Last Survey, No. **13010** Port of **London** Classed **90A.1**  
 Present Condition of the  
 Decks **Good** Treenails **Ribs** Good  
 Waterways **- do -** Breasthooks and Stems **- do -**  
 Comings **- do -** Transoms, Pointers, and Crutches **- do -**  
 Upper Deck Beams & Fastenings **- do -** Timbers of the Frame at the Openings **- do -**  
 Lower Deck Beams & Fastenings **- do -** Ditto ditto at other places **- do -**  
 Planksheers **- do -** Keelsons **- do -**  
 Sheerstrakes **Iron** Clamps and Shelves **- do -**  
 Topsides **- do -** Ceiling **- do -**  
 Wales **- do -** Rudder **- do -**  
 Plank (Bottom) and Counter **- do -** Copper or Y.M. Cement When put on **1874**  
 Caulking of Bottom, Deck, & Waterways **efficient**  
 Engine Room Skylights **good** Coal Bunker, Openings, Lids, &c. **good** Scuppers **good** Cargo and Main Hatchways **good** Hatches **good**  
 General Observations, Opinion as to Class, &c.

*The bottom cleaned and painted. This vessel is now in a good and efficient condition and in my opinion entitled to remain as classed 90A.1.*

Committee's Minute **Liverpool 4th January 1876** **J. G. Kinghorn**  
 Character assigned **90A.1**  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18

No. in Reg. Book. on the **No. 622** Survey held at **Liverpool** Date, first Survey **15 Decr** Last Survey **15th December 1875**  
**Iron S.S. "Gurtubay"** Master **de Anslage**  
 Tonnage **564-874-682** Built at **Sunderland** When built **1873**  
 By whom built **Doxford** Owners **Gurtubay**  
 Port belonging to **Bilbao** Destined Voyage **not known**  
 If Surveyed Afloat or in Dry Dock **Queen's G St**

Last Survey, No. **13428** Port of **Iron** Classed **90A.1**  
 Present Condition of the  
 Decks **Good** Treenails **Ribs** Good  
 Waterways **- do -** Breasthooks and Stems **- do -**  
 Comings **- do -** Transoms, Pointers, and Crutches **- do -**  
 Upper Deck Beams & Fastenings **- do -** Timbers of the Frame at the Openings **- do -**  
 Lower Deck Beams & Fastenings **- do -** Ditto ditto at other places **- do -**  
 Planksheers **- do -** Keelsons **- do -**  
 Sheerstrakes **Iron** Clamps and Shelves **- do -**  
 Topsides **- do -** Ceiling **- do -**  
 Wales **- do -** Rudder **- do -**  
 Plank (Bottom) and Counter **- do -** Cement When put on **1873**  
 Caulking of Bottom, Deck, & Waterways **efficient**  
 Engine Room Skylights **good** Coal Bunkers, Openings, Lids, &c. **good** Scuppers **good** Cargo and Main Hatchways **good** Hatches **good**  
 General Observations, Opinion as to Class, &c.

*The bottom cleaned and painted, a new propeller has been fitted. This vessel is now in my opinion in a good and efficient condition and entitled to remain as classed 90A.1.*

Committee's Minute **Liverpool 4th Jan 1876** **J. G. Kinghorn**  
 Character assigned **90A.1**  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18