

ANNUAL SURVEYS.

No. 3557 Survey held at West Hartlepool Date 28th Dec 1875
 on the Ship "Douglas" Master J. Pearce
 Tonnage 648 Built at Whitby When built 1873 - 3 mo
 By whom built Turnbull Owners G. P. Ryan & Co.
 Port belonging to West Hartlepool Destined Voyage Mediterranean
 If Surveyed Afloat or in Dry Dock In Dry Dock

Last Survey, No. 13888 Port of Liverpool Classed 90 A1
2.55

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>Good</u>	Breasthooks and Stemson <u>Good</u>	Pumps <u>2 or Good</u>
Comings <u>Good</u>	Transoms, Pointers, and Crutches <u>Good</u>	Boats <u>4 or Good</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame at the Openings <u>Good</u>	Masts, Yards, &c. <u>Good</u>
Lower Deck Beams & Fastenings <u>Good</u>	Ditto ditto at other places <u>Good</u>	Sails <u>Good</u>
Plank-sheers <u>Good</u>	Keelsons <u>Good where seen</u>	Anchors, No. of <u>3 Bowers / 2 / 12 lbs</u>
Sheerstrakes <u>Good</u>	Clamps and Shelves <u>Good</u>	Cables <u>Good</u>
Topsides <u>Good</u>	Ceiling <u>Good</u>	Hawsers and Warps <u>9 1/2 - 8 - 7 1/2 - 7 - 6 - 5 in. Good</u>
Wales <u>Good</u>	Rudder <u>Good</u>	Standing and Running Rigging <u>Good</u>
Plank (Bottom) and Counter <u>Good</u>	Copper <u>When put on</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

Bottom cleaned down & coated with paint & black varnish.
Is now in a good & efficient state fit for the safe conveyance of dry & perishable
goods to & from all parts of the World & may in my opinion remain as now classed
90 A1

Committee's Minute 7th January 1876

Character assigned 90 A1

Certificate (if required).

No. _____ Survey held at _____ Date _____ 18____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Sails _____
Plank-sheers _____	Keelsons _____	Anchors, No. of _____
Sheerstrakes _____	Clamps and Shelves _____	Cables _____
Topsides _____	Ceiling _____	Hawsers and Warps _____
Wales _____	Rudder _____	Standing and Running Rigging _____
Plank (Bottom) and Counter _____	Copper _____ When put on _____	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways _____

Committee's Minute _____ 18____

Character assigned _____