

ANNUAL SURVEYS.

No. in Reg. Book. **No. 13052** Survey held at **Newcastle** Date, first Survey **6th** Last Survey **10th Dec** 18 **75**
 on the S.S. **"Elphinstone"** Master **Stockdale**
 Tonnage **1146** Built at **Newcastle** When built **1874-3 mo.**
 By whom built **Palmer Co.** Owners **Hutchinson & Mc Intyre**
 Port belonging to **Newcastle** Destined Voyage **India**
 If Surveyed Afloat or in Dry Dock **Palmer Dock at Farrow**

Last Survey, No. **13526** Port of **London** Classed **90 A 1**
 Years assigned. **10.74** Character in Register Book.
 Present Condition of the Decks **gn**
 Waterways **"** Breasthooks and Stemson **gn**
 Comings **"** Transoms, Pointers, and Crutches **"**
 Upper Deck Beams & Fastenings **"** Timbers of the Frame at the Openings **"**
 Lower Deck Beams & Fastenings **"** Ditto ditto at other places **"**
 Planksheers **"** Keelsons **"**
 Sheerstrakes **"** Clamps and Shelves **"**
 Topsides **"** Ceiling **"**
 Wales **"** Rudder **"**
 Plank (Bottom) and Counter **"** Copper or Y.M. **-** When put on **-**
 Caulking of Bottom, Deck, & Waterways **gn**
 Engine Room Skylights **gn** Coal Bunker, Openings, Lids, &c. **gn** Scuppers **gn** Cargo and Main Hatchways **gn** Hatches **gn**
 General Observations, Opinion as to Class, &c.

This vessel has been in dock & bottom repainted, two plates in port-bow renewed & one frame repaired. - She is now in good condition & eligible in my opinion to remain as classed.

Committee's Minute **28th December** 18 **75**

Character assigned **90 A 1**

Damage survey fee **£3.3.0**

Geo. V. Cooper

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) **-** Paid **-** 18 **-**

No. in Reg. Book. **No. 189** Survey held at **Newcastle** Date, first Survey **12th** Last Survey **15th Dec** 18 **75**
 on the S.S. **"Langshaw"** Master **R. Bain**
 Tonnage **1187** Built at **S. Shields** When built **1875-1 mo.**
 By whom built **M. Intyre** Owners **Hutchinson & Mc Intyre**
 Port belonging to **Newcastle** Destined Voyage **India**
 If Surveyed Afloat or in Dry Dock **Palmer Dock. Farrow**

Last Survey, No. **14163** Port of **Newcastle** Classed **90 A 1**
 Years assigned. **2.75** Character in Register Book.
 Present Condition of the Decks **gn**
 Waterways **"** Breasthooks and Stemson **gn**
 Comings **"** Transoms, Pointers, and Crutches **"**
 Upper Deck Beams & Fastenings **"** Timbers of the Frame at the Openings **"**
 Lower Deck Beams & Fastenings **"** Ditto ditto at other places **"**
 Planksheers **"** Keelsons **"**
 Sheerstrakes **"** Clamps and Shelves **"**
 Topsides **"** Ceiling **"**
 Wales **"** Rudder **"**
 Plank (Bottom) and Counter **"** Copper or Y.M. **-** When put on **-**
 Caulking of Bottom, Deck, & Waterways **gn**
 Engine Room Skylights **gn** Coal Bunkers, Openings, Lids, &c. **gn** Scuppers **gn** Cargo and Main Hatchways **gn** Hatches **gn**
 General Observations, Opinion as to Class, &c.

This vessel has been recoated in bottom & a few butts recaulked. is now in good condition & eligible in my opinion to remain as classed.

Committee's Minute **28th Dec** 18 **75**

Character assigned **90 A 1**

Damage survey fee **£2.2.0**

Geo. V. Cooper

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) **-** Paid **-** 18 **-**