

# REPORT of SURVEY for REPAIRS, &c.

15611

35206

No. in g. Book. **No.** Survey held at London Date, first Survey 14<sup>th</sup> Dec<sup>r</sup> Last Survey 24<sup>th</sup> Dec<sup>r</sup> 1875  
601 on the Iron S.S. "Lord Alfred Paget" Master S. Bond  
 Tonnage under Tonnage Deck 878 Built at Newcastle When built 1870 YEAR. MONTH. 9  
 Ditto of Spar Deck, or Awning Deck Owners Clark & Co Port belonging to London  
 Ditto of Poop, or Raised Qr. Dk. Residence  
 Ditto of Houses on Deck By whom built Palmer Destined Voyage  
 Ditto of Forecastle If Surveyed Afloat or in Dry Dock Commercial dry dock  
 Gross Tonnage 982  
 Crew Space, as per Rule  
 Register Tonnage, cut on Beam  
 Engine Room  
 Reg. Tons as St'mer, cut on Bm. 621  
 Length of Poop 29 ft. Ditto, Forecastle 56 ft. Ditto, Raised Quarter Deck 56 ft. Years assigned. Character in Register Book.  
 Last Survey, No. 14849 Port London Classed 100 A 16-75  
S.S. Newc hoi 75

REPAIRS, OR EXAMINATION AS PER RULE

Through damage by collision  
 Upper piece of stem (top) new, one plate of sheerstrake starboard bow  
 taken off and rivetted. 2 Forecastle plates on the starboard side  
 and one on the Port side new, one short length of angle bar  
 to Forecastle stringer plate new. Remove bow chocks &  
 refitted

Not of damage

Bottom painted

Present Condition of the	Good	Greenails	Rivets	Good	Windlass and Capstan
Decks	---	Breasthooks and Stemson	---	---	Pumps
Waterways	---	Transoms, Pointers, and Crutches	---	---	Boats
Comings	---	Timbers of the Frame at the openings	---	---	Masts, Yards, &c.
Upper Deck Beams & Fastenings	---	Ditto Ditto at other places	---	---	Condition, how ascertained
Lower Deck Beams & Fastenings	---	Keelsons	---	---	Sails
Planksheers	---	Clamps and Shelves	---	---	Anchors No. of
Sheerstrakes	---	Ceiling	---	---	Cables
Topsides	---	Rudder	---	---	Hawsers and Warps
Wales	---	Copper Cement When put on	1870.	---	Standing & Running Rigging
Plank (Bottom) and Counter	---	Caulking of	---	---	
Engine Room Skylights	Good	Bottom, Deck, & Waterways	---	---	
Coal Bunker, Openings, Lids, &c.	Good	Scuppers	Good	Good	Cargo and Main Hatchways
General Observations, Opinion as to Class, &c.					

She is now in good condition and eligible  
 to continue as Classed

The Amount of Entry Fee ... £ 2 : - : - received by me, J. H.  
30/12/75 Special ... £ 1 : 1 : - 5 Jan 1876  
 Certificate (if required) ... £ : 5 :  
 (Travelling Expenses, if any, £ )  
 Committee's Minute 7<sup>th</sup> January 1876.  
 Character assigned 100 A 1  
Special on Damage £3. 3. 0 Dec 75 J. H.

W. B. Savoy  
J. H. Truscott  
 Surveyors to Lloyd's Register of British and Foreign Shipping.

Cause of Repairs to be clearly stated.

[The Surveyors are requested not to write on or below the space for Committee's Minute.]