

No. Survey held at London Date, first Survey Last Survey Jan 4 1876
No. in g. Book. on the S Rutlandshire 15675 Master A Jarvis
649 Tonnage 1057 Built at Birkenhead When built 1863 8 M
By whom built Clover Owners C & Ellis
Port belonging to London Destined Voyage Sydney
If Surveyed Afloat or in Dry Dock Pontoon

Last Survey, No. 13713 Port of Iron

Present Condition of the
Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunkers, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

Good Treennails Rivets

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

~~Copper or Y.M.~~ Painted When put on Now

Caulking of

Bottom, Deck, & Waterways

Good

"

"

"

"

"

"

"

"

"

Good

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors, No. of 3 Bcs. 11 1/2 lbs.

Cables

Hawsers and Warps

Standing and Running Rigging

Good

and

sufficient

where

they could

be seen

At present the bottom scraped painted &c
She is now in an efficient state of repair and
entitled to remain as classed.

Senhouse Martindale

Committee's Minute

18

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18