

No. 1102 Survey held at London Date, first Survey 20 Dec^r/75 Last Survey 21 Jan^y 1876.
Reg. Book. on the S. S. "Mirfield" 15702 Master W. Atkinson.
Tonnage 867 Built at Greenock When built 1871 — 11 mo.
By whom built Scott & Co. Owners Crawhall.
Port belonging to London Destined Voyage Black Sea.
If Surveyed Afloat or in Dry Dock in Millwall dry dock.

Last Survey, No. 12650 Port of Iron Classified 100 A.1
Years assigned. 4.74 Character in Register Book.

Present Condition of the
Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plating
(Bottom) and Counter

Engine Room Skylights

General Observations, Opinion as to Class, &c.

~~Trunnels~~

Breasthooks and Stemson

Transoms, ~~Pointers~~ and Crutches

~~Timbers~~ of the Frame at the Openings

~~Ditto~~ ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

~~Copper or Y.M. Cement~~ When put on 1871

Caulking of

Bottom, Deck, & Waterways

Coal Bunkers, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained from Deck

Sails

Anchors, No. of 3 B. 1 P. 2 R.

Cables

Hawsers and Warps

Standing and Running Rigging

Committee's Minute

Character assigned

18

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

Lloyd's Register
Foundation

IRON 464-0455