

ANNUAL SURVEYS.

No. in Reg. Book. on the No. 13704 Survey held at London Date, first Survey 11 Jan 76 Last Survey 11 Jan 76 Read 20.1.76

Supp Tonnage 1473 Built at Newcastle When built 1875 4 mo. By whom built Robinson Owners Nelson, Dublin

Port belonging to London Destined Voyage

If Surveyed Afloat or in Dry Dock Time taken dry dock

Last Survey, No. 14677 Port of Liver

Present Condition of the Decks

Classed

Years assigned.

Character in Register Book.

100 A1
6.75

Waterways

as

Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Tales

Plank (Bottom) and Counter

Engine Room Skylights

General Observations, Opinion as to Class, &c.

Treenails Quilt

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places iron

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper or Y.M.

When put on

Caulking of Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors, No. of

Cables

Hawsers and Warps

Standing and Running Rigging

Cargo and Main Hatchways

Hatches

The Bottom has now been painted and coated, and the vessel appears in good condition.

Committee's Minute

25 January

1876

Character assigned

BWV 100 A

Thos Congdon

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18

No.

Survey held at

Date, first Survey

Last Survey

18

No. in Reg. Book. on the

Master

Tonnage

Built at

When built

By whom built

Owners

Port belonging to

Destined Voyage

If Surveyed Afloat or in Dry Dock

Last Survey, No.

Port of

Classed

Years assigned.

Character in Register Book.

Present Condition of the Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

psides

les

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunkers, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper or Y.M.

When put on

Caulking of Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors, No. of

Cables

Hawsers and Warps

Standing and Running Rigging

Committee's Minute

18

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18