

# ANNUAL SURVEYS.

No. in Reg. Book. **No. 641** Survey held at **London** Date, first Survey **23<sup>rd</sup> Feb.** Last Survey **25 Feb<sup>r</sup> 1876**  
 on the **"British Peer"** Master **Clements**  
 Tonnage **1230** Built at **Belfast** When built **1865**  
 By whom built **Harland** Owners **British Ship Owners Comp<sup>y</sup>**  
 Port belonging to **Lpool** Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock **Limetiler dry dock**

Last Survey, No. **12447** Port of **London Iron** Classed **S. S. No. 2 74** Years assigned **1** Character in Register Book **74**  
 Present Condition of the Decks **Good** Reconcils **Quite** **Good**  
 Waterways **d<sup>c</sup>** Breasthooks and Stemson **d<sup>c</sup>**  
 Comings **d<sup>c</sup>** Transoms, Pointers, and Crutches **d<sup>c</sup>**  
 Upper Deck Beams & Fastenings **d<sup>c</sup>** Timbers of the Frame at the Openings **d<sup>c</sup>**  
 Lower Deck Beams & Fastenings **d<sup>c</sup>** Ditto ditto at other places **d<sup>c</sup>**  
 Planksheers **d<sup>c</sup>** Keelsons **where seen** **d<sup>c</sup>**  
 Sheerstrakes **d<sup>c</sup>** **and Cargo being on board** **d<sup>c</sup>**  
 Topsides **d<sup>c</sup>** Clamps and Shelves **d<sup>c</sup>**  
 Wales **d<sup>c</sup>** Ceiling **d<sup>c</sup>**  
~~Rails~~ (Bottom) and Counter **d<sup>c</sup>** Rudder **d<sup>c</sup>**  
 Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches  
 General Observations, Opinion as to Class, &c.

**Bottom scraped and renovated.**  
**This ship appears in good condition and eligible to remain as classed.**

Committee's Minute **3<sup>rd</sup> March** 1876 **Thos Congdon**  
 Character assigned **RA** Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date, first Survey \_\_\_\_\_ Last Survey \_\_\_\_\_ 18 \_\_\_\_  
 Reg. Book. on the \_\_\_\_\_ Master \_\_\_\_\_  
 Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_ Years assigned \_\_\_\_\_ Character in Register Book \_\_\_\_\_  
 Present Condition of the Decks \_\_\_\_\_  
 Waterways \_\_\_\_\_ Treenails \_\_\_\_\_  
 Comings \_\_\_\_\_ Breasthooks and Stemson \_\_\_\_\_  
 Upper Deck Beams & Fastenings \_\_\_\_\_ Transoms, Pointers, and Crutches \_\_\_\_\_  
 Lower Deck Beams & Fastenings \_\_\_\_\_ Timbers of the Frame at the Openings \_\_\_\_\_  
 Planksheers \_\_\_\_\_ Ditto ditto at other places \_\_\_\_\_  
 Sheerstrakes \_\_\_\_\_ Keelsons \_\_\_\_\_  
 Topsides \_\_\_\_\_ Clamps and Shelves \_\_\_\_\_  
 Wales \_\_\_\_\_ Ceiling \_\_\_\_\_  
 Plank (Bottom) and Counter \_\_\_\_\_ Rudder \_\_\_\_\_  
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches  
 General Observations, Opinion as to Class, &c.

Committee's Minute \_\_\_\_\_ 18 \_\_\_\_  
 Character assigned \_\_\_\_\_ Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18



7

11

*Edward Lloyd*



© 2019

Lloyd's Register  
Foundation