

# ANNUAL SURVEYS.

158825  
Rev 17/1/96

No. 112 Survey held at Batuman Date 23 December 1874  
on the Spanish Mercury Catalina Master Pedro de Bonqueras  
Tonnage 500 Built at Sunderland When built 1868  
By whom built Doreford Owners Yluricaga & Co  
Port belonging to Bilbao Destined Voyage Australia  
If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 15579 Port of Iron Classed A1

The present Condition of the

Decks	Tree Bails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fittings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fittings	Dito ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	Copper	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways.

*Sign of opinion this vessel is fit to carry dry and perishable cargo to and from any part of the world and that she can remain in the current as*

Committee's Minute 18

Character assigned

Lo to Act 15/2/96

*Di. J. Mars*  
Lloyd's Register  
Foundation  
Certificate (if required)

IRON465-0168