

# ANNUAL SURVEYS.

Rev 28/2/76

No. in Reg. Book. 524 No. 3576 Survey held at West Hartlepool Date, first Survey 15th Feb Last Survey 16th Feb 1876  
 on the Scow Mary Master A. Lawson  
 Tonnage 547 Built at West Hartlepool When built 1871 By whom built Denton Owners Johnston & Co.  
 Port belonging to Montrose Destined Voyage In Dry Dock  
 If Surveyed Afloat or in Dry Dock In Dry Dock

Last Survey, No. 14675 Port of Iron Classed S.L. H.L. No. 1-75 Years assigned 6.75 Character in Register Book 90A1  
 Present Condition of the Decks Good Treenails Good Windlass and Capstan Good  
 Waterways Good Breasthooks and Stems Good Pumps Two & Good  
 Comings Good Transoms, Pointers, and Crutches Good Boats Four & Good  
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good Masts, Yards, &c. Good  
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good Condition, how ascertained from Deck  
 Plank sheers Good Keelsons Good when seen Sails Good  
 Sheerstrakes Good Clamps and Shelves Good Anchors, No. of 3 Bowden 1 Stun 2 Barges  
 Topsides Good Ceiling Good Cables Good  
 Wales Good Rudder Good Hawser and Warps 10-8-7 1/2-7-6 1/2-5 1/2 Good  
 Plank (Bottom) and Counter Good Copper or Y.M. When put on Standing and Running Rigging Good  
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c. How done Bottom cleaned down & coated with paint & black varnish.  
Is now in a good & efficient state fit for the safe conveyance of dry & perishable goods to & from all parts of the World & may in my opinion remain as now Classed  
90A1  
S.L. H.L. No. 1-75.

Committee's Minute 29th February 1876 Character assigned 90A1 Surveyor to Lloyd's Register of British and Foreign Shipping. Certificate (if required) None 1876

No.            Survey held at            Date, first Survey            Last Survey            18            
 on the            Master             
 Tonnage            Built at            When built             
 By whom built            Owners             
 Port belonging to            Destined Voyage             
 If Surveyed Afloat or in Dry Dock             
 Last Survey, No.            Port of            Classed            Years assigned            Character in Register Book             
 Present Condition of the Decks            Treenails            Windlass and Capstan             
 Waterways            Breasthooks and Stems            Pumps             
 Comings            Transoms, Pointers, and Crutches            Boats             
 Upper Deck Beams & Fastenings            Timbers of the Frame at the Openings            Masts, Yards, &c.             
 Lower Deck Beams & Fastenings            Ditto ditto at other places            Condition, how ascertained             
 Plank sheers            Keelsons            Sails             
 Sheerstrakes            Clamps and Shelves            Anchors, No. of             
 Topsides            Ceiling            Cables             
 Wales            Rudder            Hawser and Warps             
 Plank (Bottom) and Counter            Copper or Y.M.            When put on            Standing and Running Rigging             
 Engine Room Skylights            Coal Bunkers, Openings, Lids, &c.            Scuppers            Cargo and Main Hatchways            Hatches             
 General Observations, Opinion as to Class, &c.           

Committee's Minute            18           Character assigned            Surveyor to Lloyd's Register of British and Foreign Shipping. Certificate (if required)            Paid            18