

ANNUAL SURVEYS.

Recd. 22.3.76.

No. in Reg. Book. on the *784* No. *14186* Survey held at *London* Date, first Survey *13 March* Last Survey *13 March* 18 *76*
 Master *Pearson*
 Tonnage *915* Built at *Hartlepool* When built *1868* 11 mo.
 By whom built *Oulton* Owners *Gray*
 Port belonging to *London* Destined Voyage
 If Surveyed Afloat or in Dry Dock *Limetile Dry dock*

Last Survey, No. *14186* Port of *London* Classed *100 A 1* 4.75
 Years assigned. *100 A 1* Character in Register Book. *4.75*
S.S. 100 A 1.72

Present Condition of the Decks	Good	Treenails	Points	Good	Windlass and Capstan
Waterways	<i>dc</i>	Breasthooks and Stemson		<i>dc</i>	
Comings	<i>dc</i>	Transoms, Pointers, and Crutches		<i>dc</i>	
Upper Deck Beams & Fastenings	<i>dc</i>	Timbers of the Frame at the Openings		<i>dc</i>	
Lower Deck Beams & Fastenings	<i>dc</i>	Ditto ditto at other places		<i>dc</i>	
Planksheers	<i>dc</i>	Keelsons <i>sent little seen</i>		<i>dc</i>	
Sheerstrakes	<i>dc</i>	Clamps and Shelves		<i>dc</i>	
Topsides	<i>dc</i>	Ceiling	<i>dc</i>	<i>dc</i>	
Wales	<i>dc</i>	Rudder		<i>dc</i>	
Blank (Bottom) and Counter	<i>dc</i>	Copper or Y.M.	When put on		
Engine Room Skylights		Caulking of Bottom, Deck, & Waterways	<i>Good</i>		
Coal Bunker, Openings, Lids, &c.		Scuppers	<i>Good</i>		
General Observations, Opinion as to Class, &c.		Cargo and Main Hatchways			
		Hatches			

Bottom scraped and recoated.
 This ship appears in good condition and eligible to remain as classed.

Surveyed with ballast on the Hold.
It is intended to frame S.S. 100.2 held on the ship's return.
 Committee's Minute *28th March* 18 *76* *Sub Congdon*

Character assigned *100 A 1* *JPW* Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. in Reg. Book. on the *84* No. *14495* Survey held at *London* Date, first Survey *17 March* Last Survey *22 March* 18 *76*
 Master *Walker*
 Tonnage *1019* Built at *Sunderland* When built *1873* 5 mo.
 By whom built *Pile* Owners *J.B. Walker*
 Port belonging to *London* Destined Voyage
 If Surveyed Afloat or in Dry Dock *Fletcher dock*

Last Survey, No. *14495* Port of *London* Classed *100 A 1* 4.75
 Years assigned. *100 A 1* Character in Register Book. *4.75*

Present Condition of the Decks	Good	Treenails	Points	Good	Windlass and Capstan
Waterways		Breasthooks and Stemson			
Comings		Transoms, Pointers, and Crutches			
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings			
Lower Deck Beams & Fastenings	<i>Good</i>	Ditto ditto at other places		<i>Good</i>	
Planksheers		Keelsons			
Sheerstrakes		Clamps and Shelves			
Topsides		Ceiling			
Wales		Rudder			
Plank (Bottom) and Counter		Copper or Y.M.	When put on		
Engine Room Skylights		Caulking of Bottom, Deck, & Waterways			
Coal Bunkers, Openings, Lids, &c.		Scuppers			
General Observations, Opinion as to Class, &c.		Cargo and Main Hatchways			
		Hatches			

Bottom cleaned and recoated. This ship appears in good condition and eligible to remain as classed.

Committee's Minute *28th March* 18 *76* *Sub Congdon*
 Character assigned *100 A 1* *JPW* Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

ALFRED BURVING



Antony



© 2019

Lloyd's Register
Foundation