

# ANNUAL SURVEYS.

Recd. 22.3.76.

No. in Reg. Book. on the *784* No. *14186* Survey held at *London* Date, first Survey *13 March* Last Survey *13 March* 18 *76*  
 Master *Pearson*  
 Tonnage *915* Built at *Hartlepool* When built *1868* 11 mo.  
 By whom built *Oulton* Owners *Gray*  
 Port belonging to *London* Destined Voyage  
 If Surveyed Afloat or in Dry Dock *Limetile Dry dock*

Last Survey, No. *14186* Port of *London* Classed *100 A 1 4.75*  
 Years assigned. *S.S. 100 1.72*

Present Condition of the Decks	<i>Good</i>	Treenails	<i>Good</i>	Character in Register Book.	
Waterways	<i>Good</i>	Breasthooks and Stemson	<i>Good</i>	<i>100 A 1 4.75</i> <i>S.S. 100 1.72</i>	
Comings	<i>Good</i>	Transoms, Pointers, and Crutches	<i>Good</i>		
Upper Deck Beams & Fastenings	<i>Good</i>	Timbers of the Frame at the Openings	<i>Good</i>		
Lower Deck Beams & Fastenings	<i>Good</i>	Ditto ditto at other places	<i>Good</i>		
Planksheers	<i>Good</i>	Keelsons	<i>Good</i>		
Sheerstrakes	<i>Good</i>	Clamps and Shelves	<i>Good</i>		
Topsides	<i>Good</i>	Ceiling	<i>Good</i>		
Wales	<i>Good</i>	Rudder	<i>Good</i>		
Plank (Bottom) and Counter	<i>Good</i>	Copper or Y.M.	When put on		
Engine Room Skylights		Caulking of Bottom, Deck, & Waterways	<i>Good</i>		
Coal Bunker, Openings, Lids, &c.		Scuppers	<i>Good</i>	Cargo and Main Hatchways	Hatches
General Observations, Opinion as to Class, &c.					

*Bottom scraped and recoated.*  
*This ship appears in good condition and eligible to remain as classed.*  
*Surveyed with ballast on the Hold.*  
*It is intended to frame S.S. 100.2 held on the ship's return.*  
 Committee's Minute *28<sup>th</sup> March* 18 *76* *Sub Congdon*  
 Character assigned *100 A 1* *JPW*  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18

No. in Reg. Book. on the *84* No. *14495* Survey held at *London* Date, first Survey *17 March* Last Survey *22 March* 18 *76*  
 Master *Walker*  
 Tonnage *1019* Built at *Sunderland* When built *1873* 5 mo.  
 By whom built *Pile* Owners *J.B. Walker*  
 Port belonging to *London* Destined Voyage  
 If Surveyed Afloat or in Dry Dock *Fletcher dock*


Last Survey, No. *14495* Port of *London* Classed *100 A 1 4.75*  
 Years assigned. *S.S. 100 1.72*

Present Condition of the Decks	<i>Good</i>	Treenails	<i>Good</i>	Character in Register Book.	
Waterways	<i>Good</i>	Breasthooks and Stemson	<i>Good</i>	<i>100 A 1 4.75</i>	
Comings	<i>Good</i>	Transoms, Pointers, and Crutches	<i>Good</i>		
Upper Deck Beams & Fastenings	<i>Good</i>	Timbers of the Frame at the Openings	<i>Good</i>		
Lower Deck Beams & Fastenings	<i>Good</i>	Ditto ditto at other places	<i>Good</i>		
Planksheers	<i>Good</i>	Keelsons	<i>Good</i>		
Sheerstrakes	<i>Good</i>	Clamps and Shelves	<i>Good</i>		
Topsides	<i>Good</i>	Ceiling	<i>Good</i>		
Wales	<i>Good</i>	Rudder	<i>Good</i>		
Plank (Bottom) and Counter	<i>Good</i>	Copper or Y.M.	When put on		
Engine Room Skylights		Caulking of Bottom, Deck, & Waterways	<i>Good</i>		
Coal Bunkers, Openings, Lids, &c.		Scuppers	<i>Good</i>	Cargo and Main Hatchways	Hatches
General Observations, Opinion as to Class, &c.					

*Bottom cleaned and recoated. This ship appears in good condition and eligible to remain as classed.*  
 Committee's Minute *28<sup>th</sup> March* 18 *76* *Sub Congdon*  
 Character assigned *100 A 1* *JPW*  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18



ALLIANCE FOR THE AMERICAN PEOPLE



*Antony*



© 2019

Lloyd's Register  
Foundation