

ANNUAL SURVEYS.

35,409
Recd. 15.4.76

No. in Reg. Book. **148** No. **148** Survey held at London Date, first Survey _____ Last Survey April 8th 1876
 on the SS Banana Master _____
 Tonnage 1227 Built at Lumberton When built 1874 8 mo.
 By whom built 1803 Smay Owners B India Ship Nav Co
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. <u>13117</u> Port of <u>London</u>		Classed <u>100A/10.74</u>			
Present Condition of the Decks		Years assigned.	Character in Register Book.		
Waterways	<u>Good</u>	} <u>Good</u>	} <u>Good</u>		
Comings	"				
Upper Deck Beams & Fastenings	"				
Lower Deck Beams & Fastenings	"				
Planksheers	"				
Sheerstrakes	"				
Topsides	"				
Wales	"				
Plank (Bottom) and Counter	"				
Engine Room Skylights	<u>Good</u>			} <u>Good</u>	} <u>Good</u>
Coal Bunker, Openings, Lids, &c.	<u>Good</u>				
General Observations, Opinion as to Class, &c.					

*All present the bottom scraped Painted &c
 She is now in an efficient state of repair
 and entitled to remain as classed*

Committee's Minute 21st April 1876 Senhouse Martindale
 Character assigned 100A/1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. in Reg. Book. **648** No. **648** Survey held at London Date, first Survey _____ Last Survey March 23 1876
 on the S Aminta Master _____
 Tonnage 1110 Built at Liverpool When built 1862 2 mo.
 By whom built Jones Owners J Smay & Co
 Port belonging to Liverpool Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. <u>13556</u> Port of <u>London</u>		Classed <u>A/1 11.74</u>			
Present Condition of the Decks		Years assigned.	Character in Register Book.		
Waterways	<u>Good</u>	} <u>Good</u>	} <u>Good</u>		
Comings	"				
Upper Deck Beams & Fastenings	"				
Lower Deck Beams & Fastenings	"				
Planksheers	"				
Sheerstrakes	"				
Topsides	"				
Wales	"				
Plank (Bottom) and Counter	"				
Engine Room Skylights	<u>Good</u>			} <u>Good</u>	} <u>Good</u>
Coal Bunkers, Openings, Lids, &c.	<u>Good</u>				
General Observations, Opinion as to Class, &c.					

*All present bottom scraped Painted &c
 She is now in an efficient state of repair
 and entitled to remain as classed*

Committee's Minute 21st April 1876 Senhouse Martindale
 Character assigned 100A/1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____