

14/46

16169

ANNUAL SURVEYS.

Rec 22/4/71

No. in Reg. Book. **1028** No. **25946** Survey held at **Liverpool** Date, first Survey **March 29** Last Survey **March 29** 18**76**
on the **(Iron) "Stoverbridge"** Master **G. Laine**
Tonnage **1499** Built at **Sunderland** When built **1869-5-11**
By whom built **Oswald** Owners **J. Nourse**
Port belonging to **London** Destined Voyage **India**
If Surveyed Afloat or in Dry Dock **In Queen's dry dock**

Last Survey, No. **14557** Port of **Liverpool** Classed ***A1-6-75-11**
Present Condition of the Decks **Good** **Reels** **Good**
Waterways **"** Breasthooks and **"**
Comings **"** Transoms, **"** and Crutches **"**
Upper Deck Beams & Fastenings **"** Timber of the Frame at the Openings **"**
Lower Deck Beams & Fastenings **"** Ditto ditto at other places **When**
Planksheers **"** Keelsons **Good**
Sheerstrakes **"** Clamps and Shelves **"**
Topsides **"** Ceiling **"**
Wales **"** Rudder **"**
Plates (Bottom) and Counter **"** Copper or Y.M. **Cen** When put on **69**
Engine Room Skylights **"** Caulking of Bottom, Deck, & Waterways **Good**
Coal Bunker, Openings, Lids, &c. **"** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
General Observations, Opinion as to Class, &c.

The bottom scraped and painted. Is now in good condition and in my opinion eligible to remain as classed -

Committee's Minute **Liverpool 21st April 1876** **E. C. Meeler**
Character assigned **A1** Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) **Paid** 18

No. **415** Survey held at **Liverpool** Date, first Survey **March 25** Last Survey **April 15** 18**76**
on the **(Iron) Bth "Polestar"** Master **McTear**
Tonnage **625** Built at **Hull** When built **1858**
By whom built **"** Owners **Cotesworth**
Port belonging to **Liverpool** Destined Voyage **America**
If Surveyed Afloat or in Dry Dock **Afloat in Queen's dry dock**

Last Survey, No. **12304** Port of **Liverpool** Classed ***A1-1-74-11**
Present Condition of the Decks **Good** **Reels** **Good**
Waterways **"** Breasthooks and **"**
Comings **"** Transoms, **"** and Crutches **"**
Upper Deck Beams & Fastenings **"** Timber of the Frame at the Openings **"**
Lower Deck Beams & Fastenings **"** Ditto ditto at other places **"**
Planksheers **"** Keelsons **"**
Sheerstrakes **"** Clamps and Shelves **"**
Topsides **"** Ceiling **"**
Wales **"** Rudder **"**
Plates (Bottom) and Counter **"** Copper or Y.M. **Cen** When put on **69**
Engine Room Skylights **"** Caulking of Bottom, Deck, & Waterways **Good**
Coal Bunkers, Openings, Lids, &c. **"** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
General Observations, Opinion as to Class, &c.

The bottom scraped and painted. Is now in good condition and in my opinion eligible to remain as classed -

Committee's Minute **Liverpool 21st April 1876** **E. C. Meeler**
Character assigned **A1** Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) **Paid** 18

"Stockbridge"

"Polestar" 25046



© 2019

Lloyd's Register
Foundation