

Run 19/5/76

No. 1067
112 Survey held at Dublin Date 10th May 1876
on the Ship "Collingwood" Master APC Ross
Tonnage 1011 Built at Aberdeen When built 1872. 6th mo
By whom built Messrs. Ross Owners Messrs. Devitt & Moore
Port belonging to London Destined Voyage Adelaide
If Surveyed Afloat or in Dry Dock In dry dock and afloat

Last Survey, No. 14035 Port of Lion

Classed 100 A1
3 mo 75

The present Condition of the

Decks
Waterways
Comings
Upper Deck Beams & Fastenings
Lower Deck Beams & Fastenings
Planksheers
Sheerstrakes
Topsides
Wales
Plating
Plank (Bottom) and Counter

Trunnails Ruvets
Breasthooks and Stemson
Transoms, Pointers, and Crutches
Timbers of the Frame at the Openings
Ditto ditto at other places
Keelsons
Clamps and Shelves
Ceiling
Rudder In good order
Copper Paint When put on

Windlass and Capstan Good
Pumps 2 in good working order
Boats 6 in good repair
Masts, Yards, &c. Good
Sails 2 Suits good
Anchors No. of 3 B. 1 S. 2 R
Cables 270 fms
Hawsers and Warps 5 good
Standing & Running Rigging Good

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good

I consider this vessel to be in a most satisfactory & efficient condition and fit to retain her Character as Classed

Committee's Minute 23rd May 1876

Character assigned 100A1

AP Allen

Surveyors not
Certificate (if required)

No. in Reg. Book 1068
113 Survey held at Dublin Date 13th 15th May 1876
on the Ship "Cape Sable" Master J Page
Tonnage 1416 Built at Glasgow When built 1874. 12th mo
By whom built Messrs. Wingate Owners Messrs. Lyle & Sons
Port belonging to Greenock Destined Voyage Australia
If Surveyed Afloat or in Dry Dock In dry dock

Last Survey, No. 13734 Port of Lion

Classed 100 A1
12-74

The present Condition of the

Decks
Waterways
Comings
Upper Deck Beams & Fastenings
Lower Deck Beams & Fastenings
Planksheers
Sheerstrakes
Topsides
Wales
Plank (Bottom) and Counter

Trunnails Ruvets
Breasthooks and Stemson
Transoms, Pointers, and Crutches
Timbers of the Frame at the Openings
Ditto ditto at other places
Keelsons
Clamps and Shelves
Ceiling
Rudder In good working order
Copper Paint When put on

Windlass and Capstan Good
Pumps 2 in good order
Boats 4 in good repair
Masts, Yards, &c. Good
Sails 2 Suits in good repair
Anchors No. of 3 B. 1 S. 2 R
Cables 170 fms
Hawsers and Warps 5 Sufficient
Standing & Running Rigging Good

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good

Committee's Minute 23rd May 1876

Character assigned 100A1

AP Allen

Surveyors not
Certificate (if required)