SS No 1 16259 35419

REPORT of SURVEY for REPAIRS, &c.

(Rec'd 22.4.76)

No. in Reg. Book. No. ✓ Survey held at London Date, first Survey March 22 Last Survey April 22 1876

398 on the SS Glenroy Master J Hogg

				YEAR.	MONTH.
TONNAGE under Tonnage Deck	2085	Built at	Glasgow	When built 1871	10
Ditto of Spar Deck, or Awning Deck		Owners	A C Gow	Port belonging to	Glasgow
Ditto of Poop, or Raised Qr. Dk.		Residence			
Ditto of Houses on Deck		By whom built	Lon & Gls Co	Destined Voyage	
Ditto of Forecastle		If Surveyed Afloat or in Dry Dock			
Gross Tonnage	2122				
Crew Space, as per Rule					
Register Tonnage, cut on Beam					
Engine Room					
Reg. Tons as St'mer, cut on Bm.	1370				

Official Number

Length of Poop ~ ft. Ditto, Forecastle ~ ft. Ditto, Raised Quarter Deck ~ ft.

Classed — Years assigned: 100 — Character in Register Book: A1 5.75

Last Survey, No. 14535 Port Iron

REPAIRS, OR EXAMINATION AS PER RULE

At the present time the vessel placed in Dry Dock the bottom Scraped painted &c.

The limbers and beiling (more than required by Rule) lifted on bothsides exposing both surfaces of plating examined and found good, bement tested which was adhering firmly to the Iron, and where worn and thin has been mended and thickened

Cause of Repairs to be clearly stated.

IRON 466 - 0156

Present Condition of the

Decks	Good	~~Treenails~~ Rivets	Good	Windlass and Capstan	Good and sufficient where they could be seen
Waterways	"	Breasthooks and Stemson	"	Pumps	
Comings	"	Transoms, Pointers, and Crutches	"	Boats	
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	Masts, Yards, &c.	
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Condition, how ascertained	
Planksheers	"	Keelsons	"	Sails	
Sheerstrakes	"	Clamps and Shelfs	"	Anchors No. of 3 Brs. St & Kedge	
Topsides	"	Ceiling	"	Cables	
Wales	"	Rudder	"	Hawsers and Warps	
~~Plank~~ (Bottom) and Counter		~~Copper~~ Painted When put on Now		Standing & Running Rigging	
		Caulking of Bottom, Deck, & Waterways	Good		

Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c.

She is now in an efficient state of repair and entitled to remain as classed, and Marked SS No 1-1876 in the Register Book

Senhouse Martindale

The Amount of Entry Fee ... ...£ : : received by me, 26th Apr 1876 A.I.T.

25/4/76 Special ... ...£ 4 : 4 :

Certificate (if required) ... ...£ - : 5 :-

(Travelling Expenses, if any, £)

Committee's Minute 28 April 1876

Character assigned 100 A1

Surveyor to Lloyd's Register of British and Foreign Shipping.

S.S. No 1-76

© 2019 Lloyd's Register Foundation

[3,000—8/3/75.]

(The Surveyors are requested not to write on or below the space for Committee's Minute.)