

16287
ANNUAL SURVEYS.

No. in Reg. Book. on the No. 3949 Survey held at Leith Date, first Survey 29th April Last Survey 4th May 1876
147 Tonnage 458 Built at Kinghorn Master Archie Campbell
By whom built Key Owners J.R. Macgregor & Co.
Port belonging to Leith Destined Voyage Antwerp.
If Surveyed Afloat or in Dry Dock In Dry Dock afloat

Last Survey, No. 3884 Port of Leith Iron Classed S.S. No 2-3 Years assigned. 6.75 Character in Register Book A.1
Present Condition of the Decks Good Rust Good
Waterways " Breasthooks and Stemson " Pinches
Comings " Transoms, Pointers, and Crutches " Windlass and Capstan Good
Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings " Pumps "
Lower Deck Beams & Fastenings " Ditto ditto at other places " Boats "
Planksheers " Keelsons " Masts, Yards, &c. "
Sheerstrakes " Clamps and Shelves " Condition, how ascertained "
Topsides " Ceiling " Sails "
Wales " Rudder " Anchors, No. of 3 B.S. 2 K "
Plank (Bottom) and Counter " Copper or Y.M. Cement When put on 1874 Cables Partly seen "
Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
General Observations, Opinion as to Class, &c. Good Standing and Running Rigging "

Bottom righted, scraped & coated with
two of red lead and one tallow.
Is now in good and efficient Condition and in
my opinion eligible to remain as classed

Committee's Minute 12th May 1876 John Parkinson
Character assigned A.1 Surveyor to Lloyd's Register of British and Foreign Shipping.
Sgt. A.D. Certificate (if required) Paid 1876

No. Survey held at Date, first Survey Last Survey 18
No. in Reg. Book. on the Master
Tonnage Built at When built
By whom built Owners
Port belonging to Destined Voyage
If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed Years assigned. Character in Register Book.
Present Condition of the Decks Treennails
Waterways Breasthooks and Stemson Windlass and Capstan
Comings Transoms, Pointers, and Crutches Pumps
Upper Deck Beams & Fastenings Timbers of the Frame at the Openings Boats
Lower Deck Beams & Fastenings Ditto ditto at other places Masts, Yards, &c.
Planksheers Keelsons Condition, how ascertained
Sheerstrakes Clamps and Shelves Sails
Topsides Ceiling Anchors, No. of
Wales Rudder Cables
Plank (Bottom) and Counter Copper or Y.M. When put on Hawfers and Warps
Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
General Observations, Opinion as to Class, &c. Standing and Running Rigging

Committee's Minute 18
Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18