

ANNUAL SURVEYS.

No. in Reg. Book. on the No. 2504 Survey held at Liverpool Date, first Survey May 12th Last Survey May 12th 1876
Ship "Sorata" Master W. Pentreath
 Tonnage 786 Built at Liverpool When built 1869 - 4 mo.
 By whom built Bowdler Owners Kalmsley & Co
 Port belonging to Liverpool Destined Voyage
 If Surveyed Afloat or in Dry Dock Canning Dry Dock.

Last Survey, No. 14860 Port of Iron Classified SS Cl. No 1-73. Years assigned. 7-75. Character in Register Book. A1
 Present Condition of the Decks Good Treennails Rivets Good
 Waterways " Breasthooks and Stems "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Paint When put on Now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights ✓ Coal Bunker, Openings, Lids, &c. ✓ Scuppers Good Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c.

Bottom sighted, cleaned and coated with paint -
She is in a good and efficient condition, eligible
in my opinion to remain as classed in

Committee's Minute 19th May 1876
 Character assigned A

J. Shilston.

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18

No. in Reg. Book. on the No. 2504 Survey held at Liverpool Date, first Survey May 12th Last Survey May 12th 1876
Ship "Lord of the Isles" Master J. Piper.
 Tonnage 657 Built at Greenock When built 1864 - 11 mo.
 By whom built Steele Owners Williamson &
 Port belonging to Liverpool Destined Voyage Calcutta.
 If Surveyed Afloat or in Dry Dock Canning Dry Dock.

Last Survey, No. 13856 Port of Iron Classified SS Lon. No 2-73. Years assigned. 1-75. Character in Register Book. A1
 Present Condition of the Decks Good Treennails Rivets Good
 Waterways " Breasthooks and Stems "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Paint When put on Now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights ✓ Coal Bunkers, Openings, Lids, &c. ✓ Scuppers Good Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c.

Bottom sighted, cleaned and coated with paint -
She is now in a good and efficient condition
eligible in my opinion to remain as classed.

Committee's Minute 19th May 1876
 Character assigned A

J. Shilston

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18

12/10/01
"Sorata"

"Lord of the Isles"

2304



© 2019

Lloyd's Register
Foundation