

ANNUAL SURVEYS.

Recd 4.5.76

No. in Reg. Book. on the 3 **No.** Scw. "Valdemar" Survey held at London Date, first Survey 5/5/76 Last Survey 5/5 1876
 Tonnage 439 Built at Newcastle When built 1866 - 11 mo.
 By whom built Leslie Owners United Ltm. Nav. Co.
 Port belonging to Copenhagen Destined Voyage Baltic
 If Surveyed Afloat or in Dry Dock in Britannia Dry Dock

Last Survey, No. 1424 Port of London Classed S.S. Nv. N-2-75. Years assigned. 4.75 Character in Register Book. A.1

Present Condition of the Decks <u>good</u>	Treenails <u>rivets</u> — <u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>d^o</u>	Breasthooks and Stemson — <u>d^o</u>	Pumps <u>d^o</u>
Comings <u>d^o</u>	Transoms, Pointers , and Crutches <u>d^o</u>	Boats <u>d^o</u>
Upper Deck Beams & Fastenings <u>d^o</u>	Timbers of the Frame at the Openings <u>d^o</u>	Masts, Yards, &c. <u>d^o</u>
Lower Deck Beams & Fastenings <u>d^o</u>	Ditto ditto at other places <u>not seen</u>	Condition, how ascertained <u>from the Deck</u>
Planksheers <u>d^o</u>	Keelsons <u>good</u>	Sails <u>good</u>
Sheerstrakes <u>d^o</u>	Clamps and Shelves <u>d^o</u>	Anchors, No. of <u>3 B. 1 S. 2 K.</u>
Topsides <u>d^o</u>	Ceiling <u>d^o</u>	Cables <u>good</u>
Wales <u>d^o</u>	Rudder <u>d^o</u>	Hawsers and Warps <u>d^o</u>
Plank (Bottom) and Counter <u>d^o</u>	Copper or Y.M. <u>Cement</u> When put on <u>67</u>	Standing and Running Rigging <u>d^o</u>
Engine Room Skylights <u>d^o</u>	Caulking of Bottom, Deck, & Waterways <u>good</u>	Cargo and Main Hatchways <u>d^o</u>
Coal Bunker, Openings, Lids, &c. <u>d^o</u>	Scuppers <u>d^o</u>	Hatches <u>d^o</u>

General Observations, Opinion as to Class, &c.

*Bottom of vessel cleaned & painted.
 Vessel is in good and efficient condition and fit in my opinion to remain as classed.*

Committee's Minute G. Mayhew 1876 J. H. Truscott
 Character assigned A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) T.B.W. Paid 18

No. Survey held at Date, first Survey Last Survey 18
 No. in Reg. Book. on the Master
 Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed Years assigned. Character in Register Book.

Present Condition of the Decks <u> </u>	Treenails <u> </u>	Windlass and Capstan <u> </u>
Waterways <u> </u>	Breasthooks and Stemson <u> </u>	Pumps <u> </u>
Comings <u> </u>	Transoms, Pointers, and Crutches <u> </u>	Boats <u> </u>
Upper Deck Beams & Fastenings <u> </u>	Timbers of the Frame at the Openings <u> </u>	Masts, Yards, &c. <u> </u>
Lower Deck Beams & Fastenings <u> </u>	Ditto ditto at other places <u> </u>	Condition, how ascertained <u> </u>
Planksheers <u> </u>	Keelsons <u> </u>	Sails <u> </u>
Sheerstrakes <u> </u>	Clamps and Shelves <u> </u>	Anchors, No. of <u> </u>
Topsides <u> </u>	Ceiling <u> </u>	Cables <u> </u>
Wales <u> </u>	Rudder <u> </u>	Hawsers and Warps <u> </u>
Plank (Bottom) and Counter <u> </u>	Copper or Y.M. <u> </u> When put on <u> </u>	Standing and Running Rigging <u> </u>
Engine Room Skylights <u> </u>	Caulking of Bottom, Deck, & Waterways <u> </u>	Cargo and Main Hatchways <u> </u>
Coal Bunkers, Openings, Lids, &c. <u> </u>	Scuppers <u> </u>	Hatches <u> </u>

General Observations, Opinion as to Class, &c.

Committee's Minute 18
 Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18