

REPORT of SURVEY for REPAIRS, &c.

Damage Repairs 16389

Recd 23. 5. 76

No. in Reg. Book. **No.** Survey held at London Date, first Survey May 12 Last Survey May 16 1876

524 on the SS Elphinstone

Master Stockdale

Official Number
 Tonnage under Tonnage Deck 1701
 Ditto of Spar Deck, or Awning Deck
 Ditto of Poop
 Ditto of Raised Qr. Dk.
 Ditto of Houses on Deck
 Ditto of Forecastle
 Gross Tonnage 1776
 Crew Space, as per Rule
 Register Tonnage, cut on Beam
 Engine Room
 Reg. Tons as St' mer, cut on Bm. 1146

Built at Newcastle When built 1874 3
 Owners J. E. M. Intyre Port belonging to Newcastle
 Residence
 By whom built Palmer Destined Voyage Nale
 If Surveyed Afloat or in Dry Dock Dry Dock

Length of Poop 12 ft. Ditto, Forecastle 12 ft. Ditto, Raised Quarter Deck 12 ft. Years assigned. 90A1 12.75 Character in Register Book.

Last Survey, No. 15591 Port London

REPAIRS, OR EXAMINATION AS PER RULE

At the present time owing to damage
 Portside two bent outside plates taken off
 straightened and replaced, 8 frame strengthened
 with additional angle iron and strained
 rivets renewed

Bottom Scraped Painted &c.

Present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Rivets <u>Good</u>	Windlass and Capstan
Waterways <u>Good</u>	Breasthooks and Stemson		Pumps
Comings <u>Good</u>	Transoms, Pointers, and Crutches		Boats
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame at the openings		Masts, Yards, &c. <u>Good</u>
Lower Deck Beams & Fastenings <u>Good</u>	Ditto Ditto at other places		Condition, how ascertained <u>and</u>
Planksheers <u>Good</u>	Keelsons		Sails <u>sufficient</u>
Sheerstrakes <u>Good</u>	Clamps and Shelves		Anchors No. of <u>3</u> <u>where</u>
Topsides <u>Good</u>	Ceiling		Cables <u>they</u>
Wales <u>Good</u>	Rudder		Hawsers and Warps <u>could</u>
Plank (Bottom) and Counter <u>Good</u>	Copper <u>Painted</u> When put on <u>New</u>		Standing & Running Rigging <u>be seen</u>
Engine Room Skylights <u>Good</u>	Caulking of		
Coal Bunker, Openings, Lids, &c. <u>Good</u>	Bottom, Deck, & Waterways <u>Good</u>		
Scuppers <u>Good</u>			
Cargo and Main Hatchways <u>Good</u>			
Hatches <u>Good</u>			

General Observations, Opinion as to Class, &c.

She is now in an efficient state of
 repair & entitled to remain as Classed

Damage Fee £3-3-0

Surveyor Marshall

The Amount of Entry Fee ... £ : : received by me, 25/5/76 Special ... £ 2 : 2 : 2nd June 1876

Certificate (if required) ... £ : :
 (Travelling Expenses, if any, £)

Committee's Minute 6 June 1876

Character assigned 90A1

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019
 Lloyd's Register
 Foundation

IRON 466-0344