

Code Sign. Letters
R.B.D.L.

16396
ANNUAL SURVEYS.

No. in Reg. Book. **No. 153.** Survey held at **Hamburg** Date, first Survey **17th May** Last Survey **20th May** 18**76**
on the **Iron Steamer, Germani** Master **J. E. Krabbe**
227 Tonnage **636** Built at **Lunderland** When built **1856**
By whom built **Laing** Owners **H. J. Perlback & Co.**
Port belonging to **Hamburg** Destined Voyage **Bordeaux**
If Surveyed Afloat or in Dry Dock **Floating Dock**

Last Survey, No. **14114** Port of **Hull Iron** Classed **80 A**
Present Condition of the
Decks **good.** Treenails **Some new rivets put in.** Windlass and Capstan **good.**
Waterways **do.** Breasthooks and Stemson **do.** Pumps **do.**
Comings **do.** Transoms, Pointers, and Crutches **do.** Boats **do.**
Upper Deck Beams & Fastenings **do.** Timbers of the Frame at the Openings **do.** Masts, Yards, &c. **do.**
Lower Deck Beams & Fastenings **good.** Ditto ditto at other places **do.** Condition, how ascertained **do.**
Planksheers **do.** Keelsons **good.** Sails **good.**
Sheerstrakes **do.** Clamps and Shelves **do.** Anchors, No. of **good.**
Topsides **do.** Ceiling **good.** Cables **do.**
Wales **do.** Rudder **good.** Hawesers and Warps **do.**
Plank (Bottom) and Counter **good.** Copper or Y.M. Patent Paint When put on **now** Standing and Running Rigging **do.**
Engine Room Skylights **good** Coal Bunker, Openings, Lids, &c. **good.** Scuppers **good.** Cargo and Main Hatchways **good** Hatches **good.**
General Observations, Opinion as to Class, &c. **The ceiling was opened at different places & also the water-tank, to see the condition of the cementing and that of the inner surface of the outside plating. All was found in a very good state, likewise the outside plating itself & all other parts of the vessel. In my opinion, she has to remain in her class.**

Committee's Minute **26th May** 18**76**

Character assigned **80 A**

Emil Ladderatz
Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) **6/** Paid **18**

No. Survey held at Date, first Survey Last Survey 18
No. in Reg. Book. on the Master
Tonnage Built at When built
By whom built Owners
Port belonging to Destined Voyage
If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed
Present Condition of the
Decks Treenails
Waterways Breasthooks and Stemson
Comings Transoms, Pointers, and Crutches
Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
Lower Deck Beams & Fastenings Ditto ditto at other places
Planksheers Keelsons
Sheerstrakes Clamps and Shelves
Topsides Ceiling
Wales Rudder
Plank (Bottom) and Counter Copper or Y.M. When put on
Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
General Observations, Opinion as to Class, &c.

Committee's Minute 18

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18