

# ANNUAL SURVEYS.

(Iron) 16398 *any*

Recd 27.5.76

No. in Reg. Book. on the **No.** 357 Survey held at London Date, first Survey 9/5/76 Last Survey 27 May 1876  
 on the Sew. Sr. "Glendale" Master W. Speck.  
 Tonnage 712 Built at W. Hartlepool When built 1874 - 1 mo.  
 By whom built Irvine Owners Steel, Young & Co.  
 Port belonging to W. Hartlepool Destined Voyage Persian Gulf.  
 If Surveyed Afloat or in Dry Dock in Commercial Dry Dock

Last Survey, No. 14698 Port of Iron Classed 90A.1  
 Years assigned. 6.75. Character in Register Book.

Present Condition of the Decks <u>good</u> Waterways <u>d°</u> Comings <u>d°</u> Upper Deck Beams & Fastenings <u>d°</u> Lower Deck Beams & Fastenings <u>d°</u> Planksheers <u>d°</u> Sheerstrakes <u>d°</u> Topsides <u>d°</u> Wales <u>d°</u> Plating (Bottom) and Counter <u>d°</u> Engine Room Skylights <u>good</u> Coal Bunker, Openings, Lids, &c. <u>d°</u> Scuppers <u>d°</u> Cargo and Main Hatchways <u>d°</u> Hatches <u>d°</u>	Treenails <u>rivets - good *</u> Breasthooks and Stemson <u>d°</u> Transoms, Pointers, and Crutches <u>d°</u> Timbers of the Frame at the Openings <u>d°</u> Ditto ditto at other places <u>not seen</u> Keelsons <u>good</u> Clamps and Shelves <u>d°</u> Ceiling <u>d°</u> Rudder <u>d°</u> Copper or Y.M. <u>Cement</u> When put on <u>74</u> Caulking of Bottom, Deck, & Waterways <u>good</u>	Windlass and Capstan <u>&amp; stem winches - good</u> Pumps <u>good</u> Boats <u>d°</u> Masts, Yards, &c. <u>d°</u> Condition, how ascertained <u>from the Deck.</u> Sails <u>good</u> Anchors, No. of <u>3 B. 1 P. 2 R.</u> Cables <u>good</u> Hawser and Warps <u>good</u> Standing and Running Rigging <u>good</u>
--	--	--

General Observations, Opinion as to Class, &c.

*The bottom of vessel examined and painted.*

*The following new hawsers have been provided viz: - 7", 6½", 6", 5", 2 of 4½", one of 4". - length of each 90 fathoms.*

*The vessel is in good and efficient condition and fit in my opinion to remain as classed.*

Committee's Minute 30<sup>th</sup> May 1876

Character assigned 90A.1

*J. H. Truscott.*  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required)        Paid        18       

No.        Survey held at        Date, first Survey        Last Survey        18         
 No. in Reg. Book. on the        Master         
 Tonnage        Built at        When built         
 By whom built        Owners         
 Port belonging to        Destined Voyage         
 If Surveyed Afloat or in Dry Dock       

Last Survey, No.        Port of        Classed         
 Years assigned.        Character in Register Book.

Present Condition of the Decks <u>      </u> Waterways <u>      </u> Comings <u>      </u> Upper Deck Beams & Fastenings <u>      </u> Lower Deck Beams & Fastenings <u>      </u> Planksheers <u>      </u> Sheerstrakes <u>      </u> Topsides <u>      </u> Wales <u>      </u> Plank (Bottom) and Counter <u>      </u> Engine Room Skylights <u>      </u> Coal Bunkers, Openings, Lids, &c. <u>      </u> Scuppers <u>      </u> Cargo and Main Hatchways <u>      </u> Hatches <u>      </u>	Treenails <u>      </u> Breasthooks and Stemson <u>      </u> Transoms, Pointers, and Crutches <u>      </u> Timbers of the Frame at the Openings <u>      </u> Ditto ditto at other places <u>      </u> Keelsons <u>      </u> Clamps and Shelves <u>      </u> Ceiling <u>      </u> Rudder <u>      </u> Copper or Y.M. <u>      </u> When put on <u>      </u> Caulking of Bottom, Deck, & Waterways <u>      </u>	Windlass and Capstan <u>      </u> Pumps <u>      </u> Boats <u>      </u> Masts, Yards, &c. <u>      </u> Condition, how ascertained <u>      </u> Sails <u>      </u> Anchors, No. of <u>      </u> Cables <u>      </u> Hawser and Warps <u>      </u> Standing and Running Rigging <u>      </u>
---	---	---

General Observations, Opinion as to Class, &c.

Committee's Minute        18       

Character assigned       

Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required)        Paid        18       

