

ANNUAL SURVEYS.

No. in Reg. Book. on the **No. 3649** Survey held at **West Hartlepool** Date, first Survey **29 May** Last Survey **18/6**
144D on the **S.S. "Golden Horn"** Master **J. Hiddor**
 Tonnage **1024** Built at **Hartlepool** When built **1865 - 4 mo**
 By whom built **Denton** Owners **W. Gray**
 Port belonging to **Hartlepool** Destined Voyage **Mediterranean**
 If Surveyed Afloat or in Dry Dock **In Dry Dock**

Last Survey, No. **15664** Port of **Iron**
 Present Condition of the
 Decks **Good** Treenails **Points Good**
 Waterways **"** Breasthooks and Stenson **"**
 Comings **"** Transoms, Pointers, and Crutches **Good**
 Upper Deck Beams & Fastenings **Good** Timbers of the Frame at the Openings **"**
 Lower Deck Beams & Fastenings **"** Ditto ditto at other places **"**
 Planksheers **"** Keelsons **not seen**
 Sheerstrakes **Good** Clamps and Shelves **"**
 Topsides **"** Ceiling **Good**
 Wales **"** Rudder **Good**
 Plank (Bottom) and Counter **Good** Copper or Y.M. **"** When put on **"**
 Caulking of Bottom, Deck, & Waterways **Good**
 Engine Room Skylights **Good** Coal Bunker, Openings, Lids, &c. **Good** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
 General Observations, Opinion as to Class, &c. **Upper Deck Part Caulked, Bottom Cleaned Down & Coated with Paint of Black Varnish**

Is now in a good & efficient state fit for the safe conveyance of dry & perishable goods to & from all parts of the World & may in my opinion remain as now
Classed 90 A1
S.S. Hpl. No. 3-73

Committee's Minute **13th June** 18 **76**
 Character assigned **90 A1**
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) **Paid** 18

No. **No.** Survey held at **Date, first Survey** Last Survey **18**
 No. in Reg. Book. on the **Master**
 Tonnage **Built at** When built
 By whom built **Owners**
 Port belonging to **Destined Voyage**
 If Surveyed Afloat or in Dry Dock

Last Survey, No. **Port of** **Classed** **Years assigned.** **Character in Register Book.**
 Present Condition of the
 Decks **Treenails**
 Waterways **Breasthooks and Stenson**
 Comings **Transoms, Pointers, and Crutches**
 Upper Deck Beams & Fastenings **Timbers of the Frame at the Openings**
 Lower Deck Beams & Fastenings **Ditto ditto at other places**
 Planksheers **Keelsons**
 Sheerstrakes **Clamps and Shelves**
 Topsides **Ceiling**
 Wales **Rudder**
 Plank (Bottom) and Counter **Copper or Y.M.** When put on **"**
 Caulking of Bottom, Deck, & Waterways **"**
 Engine Room Skylights **Coal Bunkers, Openings, Lids, &c.** Scuppers **Cargo and Main Hatchways** Hatches
 General Observations, Opinion as to Class, &c.

Committee's Minute **18**
 Character assigned
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) **Paid** 18