

ANNUAL SURVEYS.

45
 No. ~~1876~~ Survey held at Calcutta Date 1 April 1876
 on the Barque "Jamaica" Master Turner
 Tonnage 699 Built at Switzerland When built 1875 3 mo.
 By whom built Doxford Owners R. Dennistoun & Co
 Port belonging to Glasgow Destined Voyage Adelaide
 If Surveyed Afloat or in Dry Dock in dry dock

Last Survey, No. 1875 Port of London Classed 100 A1

The present Condition of the

| | | |
|--|---|---|
| Decks <u>good where seen</u> | Treenails (<u>Rivetting</u>) <u>good where seen</u> | Windlass and Capstan <u>in good order, portent wheels</u> |
| Waterways <u>"</u> | Breasthooks and Stemson <u>"</u> | Pumps <u>in good order</u> |
| Comings <u>"</u> | Transoms, Pointers, and Crutches <u>"</u> | Boats <u>4, good</u> |
| Upper Deck Beams & Fastenings <u>"</u> | Timbers of the Frame at the Openings <u>"</u> | Masts, Yards, &c. <u>all sound</u> |
| Lower Deck Beams & Fastenings <u>"</u> | <u>Ditto</u> ditto at other places <u>"</u> | Sails <u>2 good sets</u> |
| Planksheers <u>plating</u> | Keelsons <u>"</u> | Anchors, No. of <u>3 bawers, 1 stream, 2 Kedges</u> |
| Sheerstrake <u>"</u> | Clamps and Shelves <u>"</u> | Cables <u>240 fms bower, 60 fms stream</u> |
| Topsides <u>"</u> | Ceiling <u>"</u> | Hawsers and Warps <u>6 assorted</u> |
| Wales <u>"</u> | Rudder <u>good & well hung</u> | Standing and Running Rigging <u>all good</u> |
| Plank (Bottom) and Counter <u>"</u> | <u>Copper</u> Paint When put on <u>Apr 1876</u> | |

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good

A strong well built iron vessel, has been well kept and is in my opinion fit to be retained on the Register as classed.

Committee's Minute 23rd May 1876

Character assigned 100A

M. Stewart

21st April 1876.

Certificate (if required).

No. _____ Survey held at _____ Date _____ 18____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

| | | |
|-------------------------------------|--|------------------------------------|
| Decks _____ | Treenails _____ | Windlass and Capstan _____ |
| Waterways _____ | Breasthooks and Stemson _____ | Pumps _____ |
| Comings _____ | Transoms, Pointers, and Crutches _____ | Boats _____ |
| Upper Deck Beams & Fastenings _____ | Timbers of the Frame at the Openings _____ | Masts, Yards, &c. _____ |
| Lower Deck Beams & Fastenings _____ | Ditto ditto at other places _____ | Sails _____ |
| Planksheers _____ | Keelsons _____ | Anchors, No. of _____ |
| Sheerstrakes _____ | Clamps and Shelves _____ | Cables _____ |
| Topsides _____ | Ceiling _____ | Hawsers and Warps _____ |
| Wales _____ | Rudder _____ | Standing and Running Rigging _____ |
| Plank (Bottom) and Counter _____ | Copper _____ When put on _____ | |

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways _____

Committee's Minute _____ 18____

Character assigned _____



© 2019

Lloyd's Register
 Foundation
 Certificate (if required).