

*16423

Report of Survey for Repairs of Engines and Boilers.

No. _____
 Reg. Book. Survey held at London Date, first Survey 23 Feb. Last Survey May 26th 1876
 on the Screw Steamer Orwell Tons 628
 Owners Cory and Co. Port belonging to London Classified — Years assigned. — Character in Register Book. A1
4.75

Diameter of Cylinders 25" 148 1/4" Comp. Victoria Dock Engines made at Victoria Dock When made 1876
 Length of Stroke 30"
 Pressure of Steam 75 lbs
 Nominal Horse Power 80 By whom made comp. Vict. Dock. Eng Wks Co Ltd.

Particulars of Repairs and Examination New Cylinders and pistons fitted. Crank shaft taken out and trued up in lathe, after length of shaft drawn, new bush fitted in tube and new liner on shaft. All sea connections examined, and those which were ~~repaired~~ beneath the platforms have been raised above them.

New Boilers, Superheater, and Boiler seats have been fitted. In my opinion the whole of the machinery and boilers is in good order and safe working condition.

The Amount of Fee ... 19/5/76 ... £ 4: 4: received by me, James J. Milton
 Certificate (if required) ... £ : : 3 May 1876

Travelling Expenses, if any, £ _____

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute _____ 18

