

# ANNUAL SURVEYS.

No. in Reg. Book. **No.** 167 Survey held at London Date, first Survey 1873 Last Survey May 20 1876  
 on the S Samuel Plimsoll Master J. Thompson Junr & Co  
 Tonnage 1444 Built at Aberdeen When built 1873  
 By whom built How Owners J. Thompson Junr & Co  
 Port belonging to Aberdeen Destined Voyage   
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 14965 Port of Iron Classed 100A 7.75  
 Present Condition of the  
 Decks Good Treenails Rivets Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " ~~Copper or Y.M. Painted~~ When put on "  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights " Coal Bunker, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c.

*At present the bottom scraped painted &c  
 She is now in an efficient state of repair  
 and entitled to remain as classed*

Committee's Minute 30<sup>th</sup> May 18 76 Senhouse Martin  
 Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18

No. in Reg. Book. **No.** 448 Survey held at London Date, first Survey 1866 Last Survey April 26 1876  
 on the S Roman Empire Master Guncan & Co  
 Tonnage 1542 Built at N Hartlepool When built 1866  
 By whom built Pile Owners Guncan & Co  
 Port belonging to London Destined Voyage   
 If Surveyed Afloat or in Dry Dock Pontoon

Last Survey, No. 14729 Port of Iron Classed 7A1 7.75  
 Present Condition of the  
 Decks Good Treenails Rivets Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " ~~Copper or Y.M. Painted~~ When put on Now  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c.

*At present the bottom scraped painted &c  
 She is now in an efficient state of repair  
 and entitled to remain as classed*

Committee's Minute 30<sup>th</sup> May 18 76 Senhouse Martin  
 Character assigned 7A1 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18