

Row 16460
REPORT of SURVEY for REPAIRS, &c.

33 Survey held at Sunderland Date, first Survey 29th May Last Survey 1st June 1876
Row Series Steamer "Unity" Master F. Brockew
Deck 811 Built at Whitby When built 1874 MONTH 1871
Port Deck 1010 Owners R. Harrowing Port belonging to Whitby
Rule 1010 Residence Shipowners Whitby
cut on Beam 637 By whom built Turnbull Destined Voyage Coasting
mer, cut on Bm. 637 If Surveyed Afloat or in Dry Dock In Dry Dock
ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft. Years assigned 90 A. I.
vey, No. 13376 Port Whitby Iron Classed 90 A. I.

Work done:- The vessel having touched the ground during her last trip to Sulina whilst swinging she was placed in Dry Dock and the bottom sighted and examined, and it was found that she had not sustained any damage thereby. Coated the bottom with a mixture of Coal-tar, Black-Lead, and Naphtha.

Present Condition of the Decks <u>Iron and Wood</u>	Freeboards <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>Good</u>	Breasthooks and Stemson <u>Good</u>	Pumps <u>Two</u>
Comings <u>Good</u>	Transoms, Pointers, and Crutches <u>Good</u>	Boats <u>3 No</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame at the openings <u>Good</u>	Masts, Yards, &c. <u>Good</u>
Lower Deck Beams & Fastenings <u>Good</u>	Ditto Ditto at other places <u>Not seen</u>	Condition, how ascertained <u>By inquiry and observation</u>
Planksheers <u>Good</u>	Keelsons <u>Part seen</u>	Sails <u>Complete</u>
Sheerstrakes <u>Good</u>	Clamps and Shelves <u>Good</u>	Anchors No. of <u>30. 108. 216.</u>
Topsides <u>Good</u>	Ceiling <u>Good</u>	Cables <u>Part seen</u>
Wales <u>Good</u>	Rudder <u>Good</u>	Hawsers and Warps <u>5 No</u>
Plank (Bottom) and Counter <u>Good</u>	Copper <u>Large</u> When put on <u>Nov</u>	Standing & Running Rigging <u>Good</u>
Engine Room Skylights <u>Efficient</u>	Caulking of Bottom, Deck, & Waterways <u>Good</u>	Cargo and Main Hatchways <u>Good</u>
Coal Bunker, Openings, Lids, &c. <u>Secure</u>	Scuppers <u>Good</u>	Hatches <u>Good</u>
General Observations, Opinion as to Class, &c.		

She is now in good and efficient condition, and fit, in my opinion, to remain Classed 90 A. I.

The Amount of Entry Fee ... £ : : received by me, }
Special ... £ : : 187 }
Certificate (if required) ... £ : :
(Travelling Expenses, if any, £)
Committee's Minute 9 June 1876
Character assigned 90 A. I.

William S.
Surveyor to Lloyd's Register of British and Foreign Shipping.