

ANNUAL SURVEYS.

No. 1070

Survey held at Dublin

Date 2^d June

1876

on the

SS "Hibernian"

Master

John Kearns

Tonnage 204

Built at Port Glasgow

When built

1875 4 mo

By whom built

H. Murray & Co

Owners

Messrs Paul & McKenzie

Port belonging to

Dublin

Destined Voyage

Coasting

If Surveyed Afloat or in Dry Dock

In Dry Dock

Last Survey, No. 14934 Port of

Iron

Classed

90 A 1

3.5

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Planks (Bottom) and Counter

Treenails

Rivets

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shells

Ceiling

Rudder

Copper

Paint

When put on 6th mo 76

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors

Cables

Hawsers and Warps

Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Good

This vessel has now been placed on blocks in dry dock, where her hull has been thoroughly overhauled and her bottom cleaned & coated with paint & varnish - I consider her to be in a very efficient state of repair and entitled to retain her character as classed

Committee's Minute

16th June

1876

Survey fee £1. 1. 0

Character assigned

90 A 1

J.M.

Certificate (if required)