

(Iron) 16537 35552
ANNUAL SURVEYS.

Recd 28.6.76

No. in Reg. Book. **No.** 272 Survey held at London Date, first Survey 27 June Last Survey 27 June 1876
on the Ship "Sarah Grace" Master G. Hay
Tonnage 1071 Built at Port Glasgow When built 1865-4 mo.
By whom built Hill Owners Grace & Co.
Port belonging to London Destined Voyage Melbourne
If Surveyed Afloat or in Dry Dock In Fletcher's Dry Dock.

Last Survey, No. 14648 Port of Iron

Classed

Years assigned.

Character in Register Book.

*A.1
6.75

Present Condition of the

Decks good

Treenails rivets good

S. S. Liv. No. 2-73

Waterways ge

Breasthooks and Stemson ge

Windlass and Capstan good

Comings ge

Transoms, Pointers, and Crutches ge

Pumps ge

Upper Deck Beams & Fastenings ge

Timbers of the Frame at the Openings ge

Boats ge

Lower Deck Beams & Fastenings ge

Ditto ditto at other places not seen

Masts, Yards, &c. ge

Planksheers ge

Keelsons not seen on acc^t of cargo.

Condition, how ascertained from the Deck

Sheerstrakes ge

Clamps and Shelves good

Sails good

Topsides ge

Ceiling not seen on acc^t of cargo.

Anchors, No. of 3 B. 1 P. 2 H.

Wales ge

Rudder good

Cables good

Plank (Bottom) and Counter ge

Copper or Y.M. Cement When put on 165

Hawsers and Warps ge

Engine Room Skylights Coal Bunker, Openings, Lids, &c.

Caulking of Bottom, Deck, & Waterways good

Standing and Running Rigging ge

General Observations, Opinion as to Class, &c.

Scuppers good Cargo and Main Hatchways ge Hatches ge

Bottom of vessel cleaned, examined & painted.
Vessel is in good and efficient condition and fit in my opinion to remain as classed.

Committee's Minute 30 June 1876

Character assigned

J. H. Truscott.

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18

No.

Survey held at

Date, first Survey

Last Survey

18

No. in Reg. Book. on the

Master

Tonnage

Built at

When built

By whom built

Owners

Port belonging to

Destined Voyage

If Surveyed Afloat or in Dry Dock

Last Survey, No.

Port of

Classed

Years assigned.

Character in Register Book.

Present Condition of the

Decks

Treenails

Waterways

Breasthooks and Stemson

Comings

Transoms, Pointers, and Crutches

Upper Deck Beams & Fastenings

Timbers of the Frame at the Openings

Lower Deck Beams & Fastenings

Ditto ditto at other places

Planksheers

Keelsons

Sheerstrakes

Clamps and Shelves

Topsides

Ceiling

Wales

Rudder

Plank (Bottom) and Counter

Copper or Y.M. When put on

Engine Room Skylights

Coal Bunkers, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

Committee's Minute 18

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18