

ANNUAL SURVEYS.

33616
Rec. 19.7.76

No. in Reg. Book. **98** No. **15326** Survey held at **London** Date, first Survey **5th July** Last Survey **5th July** 18 **76**
on the Ship **"Lady Jocelyn"** Master **J Jenkins**
Tonnage **213 1/8** Built at **London** When built **1852**
By whom built **cfb are** Owners **Partly Bros**
Port belonging to **London** Destined Voyage
If Surveyed Afloat or in Dry Dock **Thames Graving Dock**

Last Survey, No. **15326** Port of **Iron** Classed **S.S. No 2-75** Years assigned **10-75** Character in Register Book **A.1.**
Present Condition of the Decks **Good** Treennails **Rivets** **Good**
Waterways **"** Breasthooks and Stems **"**
Comings **"** Transoms, Pointers, and Crutches **"**
Upper Deck Beams & Fastenings **"** Timbers of the Frame at the Openings **"**
Lower Deck Beams & Fastenings **"** Ditto ditto at other places **"**
Planksheers **"** Keelsons **"**
Sheerstrakes **"** Clamps and Shelves **"**
Topsides **"** Ceiling **"**
Wales **"** Rudder **"**
Plank (Bottom) and Counter **"** Copper or Y.M. **Cent** When put on
Engine Room Skylights **"** Coal Bunker, Openings, Lids, &c. **"** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
General Observations, Opinion as to Class, &c. **Bottom and keel sighted cleaned and coated with Patent Composition and the topsides with Paint**

This Vessel is now in good and efficient condition and eligible to remain as Classed.

Committee's Minute **25th July** 18 **76** Character assigned **A.1.** Surveyor to Lloyd's Register of British and Foreign Shipping. Certificate (if required) **Paid** 18

No. in Reg. Book. **486** No. **14594** Survey held at **London** Date, first Survey **July** Last Survey **July** 18 **76**
on the Ship **"Rodney"** Master **Loutitt**
Tonnage **144 1/2** Built at **Glasgow** When built **1874-3 mo**
By whom built **Pile** Owners **Smith & Moore**
Port belonging to **London** Destined Voyage
If Surveyed Afloat or in Dry Dock **Thames Graving Dock**

Last Survey, No. **14594** Port of **Iron** Classed **100 A.1** Years assigned **6-75** Character in Register Book **A.1.**
Present Condition of the Decks **Good** Treennails **Rivets** **Good**
Waterways **"** Breasthooks and Stems **"**
Comings **"** Transoms, Pointers, and Crutches **"**
Upper Deck Beams & Fastenings **"** Timbers of the Frame at the Openings **"**
Lower Deck Beams & Fastenings **"** Ditto ditto at other places **"**
Planksheers **"** Keelsons **"**
Sheerstrakes **"** Clamps and Shelves **"**
Topsides **"** Ceiling **"**
Wales **"** Rudder **"**
Plank (Bottom) and Counter **"** Copper or Y.M. **Cent** When put on **1874**
Engine Room Skylights **"** Coal Bunker, Openings, Lids, &c. **"** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
General Observations, Opinion as to Class, &c. **Bottom and keel sighted cleaned and coated with Patent Composition and the topsides with Paint.**

This Vessel is now in good and efficient condition and eligible to remain as Classed.

Committee's Minute **25th July** 18 **76** Character assigned **100 A.1.** Surveyor to Lloyd's Register of British and Foreign Shipping. Certificate (if required) **Paid** 18