

ANNUAL SURVEYS.

35,597

Recd 13.7.76

No. in Reg. Book. on the 104 No. 1777 Survey held at London Date, first Survey 7 July Last Survey 7 July 1876
 Master S. L.
 Tonnage 1777 Built at Liverpool When built 1874 - 10 mo.
 By whom built Potter Owners Smith, Bilbrough & Co.
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Regent Dry Dock.

Last Survey, No. 13914 Port of Liverpool Classed 100 A.1
 Years assigned. 1.75 Character in Register Book. _____
 Present Condition of the Decks good
 Waterways 8- Treenails rivets good
 Comings 8- Breasthooks and Stemson 8-
 Upper Deck Beams & Fastenings 8- Transoms, Pointers, and Crutches 8-
 Lower Deck Beams & Fastenings 8- Timbers of the Frame at the Openings 8-
 Planksheers 8- Ditto ditto at other places not seen
 Sheerstrakes 8- Keelsons good
 Topsides 8- Clamps and Shelves 8-
 Wales 8- Ceiling 8-
 Plank (Bottom) and Counter 8- Rudder 8-
 Engine Room Skylights Coal Bunker, Openings, Lids, &c. Copper or Y.M. Clement When put on 174
 Caulking of Bottom, Deck, & Waterways good
 Scuppers good Cargo and Main Hatchways 8- Hatches 8-

General Observations, Opinion as to Class, &c. Bottom vessel painted.
Vessel is in good and efficient Condition
and fit in our opinion to remain as classed

Committee's Minute 21st July 1876 J. H. Truscott
 Character assigned 100 A.1 His Condon
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. in Reg. Book. on the _____ No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18 _____
 Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____
 Years assigned. _____ Character in Register Book. _____
 Present Condition of the Decks _____
 Waterways _____ Treenails _____
 Comings _____ Breasthooks and Stemson _____
 Upper Deck Beams & Fastenings _____ Transoms, Pointers, and Crutches _____
 Lower Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Planksheers _____ Ditto ditto at other places _____
 Sheerstrakes _____ Keelsons _____
 Topsides _____ Clamps and Shelves _____
 Wales _____ Ceiling _____
 Plank (Bottom) and Counter _____ Rudder _____
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Copper or Y.M. _____ When put on _____
 Caulking of Bottom, Deck, & Waterways _____
 Scuppers _____ Cargo and Main Hatchways _____ Hatches _____

General Observations, Opinion as to Class, &c. _____
 Committee's Minute _____ 18 _____
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

IRON 467-0237