

REPORT of SURVEY for REPAIRS, &c.

Rec 27/7/76

No. in Reg. Book. **334** No. **4479** Survey held at **Hull** Date, first Survey **2nd May** Last Survey **19th May** 18**76**
 on the **Hon^{ble} Bt "Don Antonio"** Master _____
 Tonnage **1109** built at **Glasgow** When built **1860**
 By whom built **Hill** Owners **Bailey & Leckham (Hull)**
 Port belonging to **Lisbon** Destined Voyage **Lisbon**
 If Surveyed Afloat or in Dry Dock **On Scales No 2 Slip & afloat in Albert Dock**

Last Survey, No. **14782** Port **Iron** Classed **SS Hull No 2-75** Years assigned. **100A1** Character in Register Book. **7-75**

REPAIRS, OR EXAMINATION AS PER RULE

The Stowage Coal Bunker examined in accordance with Hull Report No 4394.

Ceiling lifted at several places in other holds and relaid or renewed as required

Main and Poop deck Caulked

Cause of Repairs to be clearly stated.

Present Condition of the

Decks	<i>Good when seen</i>	Iron <i>Nails</i>	<i>Good when seen</i>	Windlass and Capstan	<i>Good when seen</i>				
Waterways		Breasthooks and Stemson		Pumps					
Comings		Transoms, Pointers, and Crutches		Boats					
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.					
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained					
Planksheers		Keelsons		Sails					
Sheerstrakes		Clamps and Shelves		Anchors No. of					
Topsides		Ceiling		Cables					
Wales		Rudder		Hawsers and Warps					
Plank (Bottom) and Counter		Copper When put on		Standing & Running Rigging					
Engine Room Skylights	<i>Good</i>	Coal Bunker, Openings, Lids, &c.	<i>Good</i>	Scuppers	<i>Good</i>	Cargo and Main Hatchways	<i>Good</i>	Hatches	<i>Good</i>

General Observations, Opinion as to Class, &c.

Is now in good condition and eligible in my opinion to remain as classed 100A1

The Amount of Entry Fee ... £ ... received by me, **100**
 Special ... £ **3** : **3** : **25th July 1876**
 Certificate (if required) ... £ ...

(Travelling Expenses, if any, £ ...) Committee's Minute **28th July** 18**76**

Character assigned **100A1**

Mr Davidson
 Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register Foundation

IRON 457-0322