

# ANNUAL SURVEYS.

No. in Reg. Book. on the **No.** *471* Survey held at *London* Date, first Survey *21 July* Last 'rvey *24 July* 18*76*.  
*Lisbon* *Scw. Bq.* Master *J. E. Hall.*  
 Tonnage *860* Built at *West Hartlepool.* When built *1871-7 mo.*  
 By whom built *Denton* Owners *J. Hall & Co.*  
 Port belonging to *London* Destined Voyage *Lisbon.*  
 If Surveyed Afloat or in Dry Dock *Fletcher's Dry Dock*

Last Survey, No. *\*14672* Port of *London* Classed *S.S. No 1-75.* Years assigned. *100 A.1* Character in Register Book. *6.75.*  
 Present Condition of the  
 Decks *good* Treenails *rivets* *good*  
 Waterways *good* Breasthooks and Stemson *good*  
 Comings *good* Transoms, Pointers, and Crutches *good*  
 Upper Deck Beams & Fastenings *good* Timbers of the Frame at the Openings *good*  
 Lower Deck Beams & Fastenings *good* Ditto ditto at other places *not seen*  
 Plank sheers *good* Keelsons *good*  
 Sheerstrakes *good* Clamps and Shelves *good*  
 Topsides *good* Ceiling *good*  
 Rudder *good*  
 Copper or Y.M. Cement When put on *1871*  
 Caulking of Bottom, Deck, & Waterways *good*  
 Windlass and Capstan *good*  
 Pumps *good*  
 Boats *good*  
 Masts, Yards, &c. *good*  
 Condition, how ascertained *from the Deck*  
 Sails *good*  
 Anchors, No. of *3 B. 1 P. 2 R.*  
 Cables *good*  
 Hawesers and Warps *good*  
 Standing and Running Rigging *good*  
 Engine Room Skylights *good* Coal Bunker, Openings, Lids, &c. *good* Scuppers *good* Cargo and Main Hatchways *good* Hatches *good*  
 General Observations, Opinion as to Class, &c.

*A few rivets renewed in the extreme after end of keel. Bottom examined and painted. Vessel is in good and efficient condition and fit in my opinion to remain as classed.*

Committee's Minute *28th July* 18*76*

Character assigned *100 A.1*

*J. St. Truscott.*

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18

No. Survey held at Date, first Survey Last Survey 18  
 No. in Reg. Book. on the Master  
 Tonnage Built at When built  
 By whom built Owners  
 Port belonging to Destined Voyage  
 If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed Years assigned. Character in Register Book.  
 Present Condition of the  
 Decks Treenails  
 Waterways Breasthooks and Stemson  
 Comings Transoms, Pointers, and Crutches  
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings  
 Lower Deck Beams & Fastenings Ditto ditto at other places  
 Plank sheers Keelsons  
 Sheerstrakes Clamps and Shelves  
 Topsides Ceiling  
 Rudder  
 Copper or Y.M. When put on  
 Caulking of Bottom, Deck, & Waterways  
 Windlass and Capstan  
 Pumps  
 Boats  
 Masts, Yards, &c.  
 Condition, how ascertained  
 Sails  
 Anchors, No. of  
 Cables  
 Hawesers and Warps  
 Standing and Running Rigging  
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches  
 General Observations, Opinion as to Class, &c.

Committee's Minute 18

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18